# COVERING NOTE

Geneva, 31 March 2005

ITU – TELECOMMUNICATION
STANDARDIZATION SECTOR

Subject: Erratum 1 (03/2005) to

ITU-T Recommendation G.783 (02/2004), *Characteristics of synchronous digital hierarchy (SDH) equipment functional blocks*

1)   Add the missing legend "MSnP4fsh" in Figure 11-37/G.783 as follows:

a) Span switch

b) Ring switch

G.783_F11-37

2)　　　*In Table 12-40/G.783, correct header as follows:*

S4-Xc_CI column	S4_CI number	S4-Xv_CI column
$X + 1$	1	2
...	...	...
$2 \times X$	X	2
$2 \times X + 1$	1	3
...	...	...
$261 \times X$	X	261