



COVERING NOTE

GENERAL SECRETARIAT INTERNATIONAL TELECOMMUNICATION UNION


Geneva, 29 March 2004

ITU – TELECOMMUNICATION
STANDARDIZATION SECTOR

Subject: Erratum 1 (03/2004) to

ITU-T Recommendation X.151 (10/2003), *Frame Relay operations and maintenance*
– *Principles and functions*

Replace Figure 2/X.151 "Location of OAM Maintenance Points (FROMPs) for monitoring performance" by the following, to show the Monitor points in the edge switches:



X.151_F2