




| Equip. Category | Problem | Main Reasons | Effects | |
|-------------------------|--|---|---|--|
| Analog Voice Gateway | Can't forward dialed digits to next devise. | Feature not supported and not mentioned on Data Sheet although it is basic requirements for operation. | Another device should be used. | |
| Voice interface Card | Caller ID feature is not working on certain mode of operation although it is globally mentioned on Spec. Sheet that it is supported. | New hardware interface card should be used. | The customer was unsatisfied and switched to another vendor. | |
| Data Switch | Per Packet load sharing on multi-trunk lines is not working although it is mentioned in the Spec. Sheet | Function not available in current software release. | Additional devices need to be used to support the required function. | |
| WiMAX Base-station | Antenna diversity should be supported It is available on the configuration menu but not working. | The diversity is actually not working when it was enabled on the software | support Team stated that the diversity is not working in the current software and may be active in next version | |



















| Company Name | ITU Code | Testing Route | Product | Category | ITU-T Recommendation (s) | SDOs |
|-----------------|--------------------------|------------------|------------------------------|----------|--|---|
| Company | ITU-T- C3- 0000154 | 3 | DSL-wifi Modem X3/1234 | ADSL | ITU-T G.992.2 (1999-07) ITU-T G.992.5 (2009-01) ITU-T G.994.1 (2007-02) | DSL Forum, ATIS (Alliance for Telecommunications) Industry Solutions) IEEE (Institute of Electrical and Electronics Engineers) |


7

| Search in the database 🛛 🙀 | | | | | | | |
|---|--|--|--|--|--|--|--|
| DISCLAIMER This database is not certified to be either accurate or complete, but only reflects the information that has been communicated to the ITU secretariat. The ITU secretariat has not verified the veracity or accuracy of such information, nor the relevance of the products to ITU Recommendations | | | | | | | |
| C Search here | | | | | | | |
| Company: - All - 💌 | | | | | | | |
| Product Category: - All - | | | | | | | |
| Testing Route: - All - | | | | | | | |
| ITU Code: | | | | | | | |
| Product Name: | | | | | | | |
| ITU-T Recommendation: | | | | | | | |
| SDOs: | | | | | | | |
| Search Reset | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| 5 | | | | | | | |
| | | | | | | | |
| | | | | | | | |

| Labs Search | | | | | | |
|--|---|--|--|--|--|--|
| | DISCLAIMER eflects the information that has been communicated to the ITU secretariat. The ITU secretariat has rmation. For additional information please contact the laboratory directly. | | | | | |
| C Search here | | | | | | |
| Laboratory Name: Country: | | | | | | |
| Categories of tested products: | | | | | | |
| ITU-T Recommendation(s) Implemented: | | | | | | |
| Product Name: | | | | | | |
| Accreditation Status: | - ALL - 💟 | | | | | |
| MRAs Status: | - ALL - 💌 | | | | | |
| | Search Reset | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |













<section-header><section-header><section-header><section-header><text><text><list-item><list-item>








































19



