



International Telecommunication Union
Radiocommunication Bureau

BR IFIC No / Date
BR IFIC No / Date
BR IFIC No / Fecha

2781 / 28.10.2014

Section Spéciale No
Special Section No
Sección Especial No

GE75/141

Date limite pour la réception des commentaires :
Expiry date for the receipt of comments :
Fecha límite para la recepción de los comentarios :

17.02.2015

	En-têtes des colonnes	Columns headings	Titulos de las columnas
AMS	PLN (Plan) ADD(Addition) MOD(modification) SUP(Suppression)	PLN (Plan) ADD(Addition) MOD(modification) SUP(Suppression)	PLN (Plan) ADD(Adición) MOD(modificación) SUP(Anulación)
Id No	Numéro d'identification du BR	BR identification number	Número de identificación de la BR
JN	Opération : HJ(jour), HN(Nuit)	Operation : HJ (Day-time), HN(Night-time)	Operación : HJ (día) o HN (noche)
Freq	Fréquence assignée, kHz	Assigned frequency, kHz	Frecuencia asignada, kHz
Sync	S pour réseau synchronisé	S for a synchronized network	S para una red sincronizada
Site name	Nom de l'emplacement d'émission	Name of the transmitter site	Nombre del emplazamiento de transmisión
Ctry	Symbole de pays ou zone géographique	Country or geographical zone symbol	Símbolo del país o zona geográfica
Geocoords	Coordonnées géographiques	Geographical coordinates	Coordenadas geográficas
Pr	Rapport de protection canal adjacent	Adjacent channel protection ratio	Relación de protección en canal adyacente
Bdw	Largeur de bande, kHz	Bandwidth, kHz	Anchura de banda, kHz
Power	Puissance de l'onde porteuse, kW	Carrier power, kW	Potencia de la portadora, kW
Emrp	Rayonnement maximal, dB(kW)	Maximum radiation, dB(kW)	Radiación máxima, dB(kW)
Azm	Azimet de rayonnement maximal	Azimuth of maximum radiation	Acimut de radiación máxima
Ant	Type d'antenne, A ou B	Antenna type, A or B	Tipo de antena, A o B
Hgt	Hauteur de l'antenne, m	Height of antenna, m	Altura de la antena, m
Cond	Conductivité du sol, mS/m	Ground conductivity, mS/m	Conductividad del suelo, mS/m
Rmks	Commentaires du BR	Comments of the BR	Comentarios de la BR
Coord A	Coordination effectuée	Coordination effected	Coordinación efectuada
Coord B	Coordination nécessaire	Coordination required	Coordinación a efectuar

Partie / Part / Parte A

AMS	Id No	JN	Freq	Sync	Site name	Ctry	Geocoords	Pr	Bdw	Power	Emrp	Azm	Ant	Hgt	Cond	Rmks	Coord_A	Coord_B
PLN	075000573	HJ	576	S	DONGCHUAN	CHN	103E12 26N06	5	20	10	10.0		A	66	10			
PLN	075000573	HN	576	S	DONGCHUAN	CHN	103E12 26N06	5	20	10	10.0		A	66	10			
MOD	114089409	HJ	576	S	FUNING	CHN	105E36 23N38	9	20	10	10.6		A	172	3			
MOD	114089409	HN	576	S	FUNING	CHN	105E36 23N38	9	20	10	10.6		A	172	3			
PLN	075000579	HJ	576	S	QIUBEI	CHN	104E11 24N02	9	20	50	17.4		A	120	1			
PLN	075000579	HN	576	S	QIUBEI	CHN	104E11 24N02	9	20	50	17.4		A	120	1			
MOD	114089408	HJ	576	S	KUNMING 2	CHN	102E45 25N07	9	20	200	25.1		A	260	3			
MOD	114089408	HN	576	S	KUNMING 2	CHN	102E45 25N07	9	20	65	20.2		A	260	3			LAO; RUS
ADD	114089411	HJ	603	S	ZHENGZHOU 2	CHN	113E51 34N50	9	20	200	25.1		A	249	3			
ADD	114089411	HN	603	S	ZHENGZHOU 2	CHN	113E51 34N50	9	20	100	26.0		B		3			KOR; MNG
ADD	114089417	HJ	639	S	XINDU	CHN	104E07 30N54	9	20	100	26.0		B		30			
ADD	114089417	HN	639	S	XINDU	CHN	104E07 30N54	9	20	100	26.0		B		30			IND; LAO; RUS
PLN	075001406	HJ	684	S	DANGCHANG	CHN	104E25 33N55	9	20	10	10.4		A	120	3			
PLN	075001406	HN	684	S	DANGCHANG	CHN	104E25 33N55	9	20	10	10.4		A	120	3			
MOD	114089415	HJ	684	S	LONGXI	CHN	104E39 34N57	9	20	200	25.1		A	219	3			
MOD	114089415	HN	684	S	LONGXI	CHN	104E39 34N57	9	20	45	18.6		A	219	3			
PLN	075001828	HJ	738		IN AMENAS	ALG	009E38 28N03	0	9	400	31.0	90	B		1			
PLN	075001828	HN	738		IN AMENAS	ALG	009E38 28N03	0	9	400	31.0	90	B		1			
MOD	114094170	HJ	738		IN AMENAS	ALG	009E38 28N03	0	9	300	25.1		A	101	1			
MOD	114094170	HN	738		IN AMENAS	ALG	009E38 28N03	0	9	100	20.4		A	101	1			
ADD	114089412	HJ	738	S	XIANGTAN	CHN	112E58 27N52	9	20	200	25.1		A	203	30			
ADD	114089412	HN	738	S	XIANGTAN	CHN	112E58 27N52	9	20	100	26.0		B		30			J; LAO; PHL; VTN
PLN	075002022	HJ	756	S	YICHUN 2	CHN	128E45 47N40	9	20	50	17.4		A	90	3			
PLN	075002022	HN	756	S	YICHUN 2	CHN	128E45 47N40	9	20	50	17.4		A	90	3			
MOD	114089416	HJ	756	S	HARBIN 1	CHN	126E50 45N42	9	20	150	28.8		B		10			
MOD	114089416	HN	756	S	HARBIN 1	CHN	126E50 45N42	9	20	150	23.9		B		10			J; KOR; KRE; RUS
PLN	075002420	HJ	810	S	NINGBO	CHN	121E32 29N52	9	20	50	17.4		A	90	3			
PLN	075002420	HN	810	S	NINGBO	CHN	121E32 29N52	9	20	50	17.4		A	90	3			
MOD	114089406	HJ	810	S	HANGZHOU 1	CHN	120E05 30N20	9	20	200	25.1		A	185	3			
MOD	114089406	HN	810	S	HANGZHOU 1	CHN	120E05 30N20	9	20	200	29.0		B		3			KOR; KRE; PHL
ADD	114089418	HJ	873	S	HARBIN 1	CHN	126E50 45N42	9	20	150	23.9		A	172	10			
ADD	114089418	HN	873	S	HARBIN 1	CHN	126E50 45N42	9	20	150	23.9		B		10			J; KOR; KRE; RUS
PLN	108041069	HJ	918		ARKHANGELSK KOSKOVO	RUS	041E23 64N21	9	16	150	24.8		A	210	3			
PLN	108041069	HN	918		ARKHANGELSK KOSKOVO	RUS	041E23 64N21	9	16	150	24.8		A	210	3			
MOD	114112340	HJ	918	S	ARKHANGELSK KOSKOVO	RUS	040E08 64N21	9	16	150	24.8		A	210	3			
MOD	114112340	HN	918	S	ARKHANGELSK KOSKOVO	RUS	040E08 64N21	9	16	150	24.8		A	210	3			SVN

Partie / Part / Parte A

<u>AMS</u>	<u>Id No</u>	<u>JN</u>	<u>Freq</u>	<u>Sync</u>	<u>Site name</u>	<u>Ctry</u>	<u>Geocoords</u>	<u>Pr</u>	<u>Bdw</u>	<u>Power</u>	<u>Emrp</u>	<u>Azm</u>	<u>Ant</u>	<u>Hgt</u>	<u>Cond</u>	<u>Rmks</u>	<u>Coord_A</u>	<u>Coord_B</u>
PLN	075003258	HJ	927	S	LUODIAN	CHN	106E40 25N29	9	20	50	17.4		A	90	1			
PLN	075003258	HN	927	S	LUODIAN	CHN	106E40 25N29	9	20	50	17.4		A	90	1			
MOD	114089414	HJ	927	S	KAILI	CHN	107E57 26N34	9	20	200	25.1		A	162	1			
MOD	114089414	HN	927	S	KAILI	CHN	107E57 26N34	9	20	105	22.3		B		1			RUS; THA
PLN	106062027	HJ	1008		TUAPSE	RUS	039E04 44N06	9	16	1	0.4		A	75	3			
PLN	106062027	HN	1008		TUAPSE	RUS	039E04 44N06	9	16	1	0.4		A	75	3			
MOD	114111896	HJ	1008		TUAPSE	RUS	039E04 44N06	9	16	5	8.0		B		3			
MOD	114111896	HN	1008		TUAPSE	RUS	039E04 44N06	9	16	5	7.4		A	75	3			
PLN	075004055	HJ	1026	S	JIANHE	CHN	108E45 26N39	9	20	50	17.4		A	70	1			
PLN	075004055	HN	1026	S	JIANHE	CHN	108E45 26N39	9	20	50	17.4		A	70	1			
MOD	114089413	HJ	1026	S	XIUWEN	CHN	106E43 26N52	9	20	200	25.1		A	146	1			
MOD	114089413	HN	1026	S	XIUWEN	CHN	106E43 26N52	9	20	105	22.3		B		1			AUS; J; LAO; PHL; RUS; THA
ADD	114089419	HJ	1116	S	HARBIN 1	CHN	126E50 45N42	9	20	120	22.9		A	134	10			
ADD	114089419	HN	1116	S	HARBIN 1	CHN	126E50 45N42	9	20	15	13.9		A	134	10			RUS
ADD	114089420	HJ	1170	S	JIAN	CHN	114E59 26N49	9	20	600	29.9		A	128	30			
ADD	114089420	HN	1170	S	JIAN	CHN	114E59 26N49	9	20	600	36.8		B		30			PHL
PLN	075005484	HJ	1215	S	PANSHAN	CHN	122E02 41N08	9	20	5	7.4		A	60	3			
PLN	075005484	HN	1215	S	PANSHAN	CHN	122E02 41N08	9	20	5	7.4		A	60	3			
MOD	114089410	HJ	1215	S	SHENYANG	CHN	123E18 41N37	9	20	10	12.1		A	123	10			
MOD	114089410	HN	1215	S	SHENYANG	CHN	123E18 41N37	9	20	10	12.1		A	123	10			KOR
PLN	075005572	HJ	1224		PINGXIANG GX	CHN	106E45 22N11	9	20	10	10.4		A	60	3			
PLN	075005572	HN	1224		PINGXIANG GX	CHN	106E45 22N11	9	20	10	10.4		A	60	3			
MOD	114089407	HJ	1224	S	NANNING 1	CHN	108E11 22N47	9	20	100	22.1		A	123	30			
MOD	114089407	HN	1224	S	NANNING 1	CHN	108E11 22N47	9	20	100	26.0		B		30			THA
ADD	114089421	HJ	1323	S	SHUANGYASHAN 1	CHN	131E12 46N43	9	20	200	25.1		A	113	1			
ADD	114089421	HN	1323	S	SHUANGYASHAN 1	CHN	131E12 46N43	9	20	200	25.1		B		1			J; KOR; KRE; RUS
ADD	114088319	HJ	1503		SHIN ONSENCHO	J	134E29 35N35	9	15	0.5	-2.6		A	45	3			
ADD	114088319	HN	1503		SHIN ONSENCHO	J	134E29 35N35	9	15	0.5	-2.6		A	45	3			

Annexe à la Partie / Annex to Part / Anexo a la Parte A

AMS	<i>Id No</i>	<i>JN</i>	<i>Freq</i>	<i>Sync</i>	<i>Site name</i>	<i>Ctry</i>	00	01	02	03	04	05	06	07	08		09	10	11	12	13	14	15	16	17		18	19	20	21	22	23	24	25	26		27	28	29	30	31	32	33	34	35	
ADD	114089411	HN	603	S	ZHENGZHOU 2	CHN	-1	-2	-3	-4	-4	-4	-3	-19	-3		-4	-4	-4	-3	-2	-1	1	2	-3		-7	5	5	-4	6	6	6	6	6		6	6	-4	5	5	-7	-3	2	1	
ADD	114089417	HJ	639	S	XINDU	CHN	6	6	6	6	6	5	5	4	3		2	1	-1	-2	-3	-4	-4	-4	-3		-3	-3	-4	-4	-4	-3	-5	-4	1		2	3	4	5	5	6	6	6	6	
ADD	114089417	HN	639	S	XINDU	CHN	6	6	6	6	6	5	5	4	3		2	1	-1	-2	-3	-4	-4	-4	-3		-3	-3	-4	-4	-4	-3	-2	-1	1		2	3	4	5	5	6	6	6	6	
ADD	114089412	HN	738	S	XIANGTAN	CHN	6	6	6	5	5	4	3	2	1		-5	-2	-3	-9	-8	-4	-13	-3	-13		-4	-8	-9	-3	-2	-5	1	2	3		4	5	5	6	6	6	6	6	6	
MOD	114089416	HJ	756	S	HARBIN 1	CHN	1	4	6	6	7	6	6	4	1		-2	-7	-15	-28	-55	-30	-19	-14	-11		-10	-10	-11	-11	-11	-11	-11	-10	-10		-11	-11	-19	-30	-55	-28	-15	-7	-2	
MOD	114089416	HN	756	S	HARBIN 1	CHN	2	2	2	2	2	1	1	0	-1		-2	-3	-5	-6	-7	-8	-8	-8	-7		-7	-7	-8	-8	-8	-7	-6	-5	-3		-2	-1	0	1	1	2	2	2	2	
MOD	114089406	HN	810	S	HANGZHOU 1	CHN	5	0	3	-5	1	-4	-4	-3	-4		-4	-4	-3	-3	-3	-4	-4	-4	-3		-4	-4	1	-5	3	0	-2	5	6		6	6	6	6	6	6	6	6	-2	
ADD	114089418	HN	873	S	HARBIN 1	CHN	-4	-4	-3	-5	-6	-7	-8	-8	-8		-7	-7	-7	-8	-8	-8	-7	-10	-10		-3	-2	-1	0	1	1	2	2	2		2	2	2	2	-2	2	1	1	0	
MOD	114089414	HN	927	S	KAILI	CHN	1	0	2	2	2	2	2	2	2		2	2	2	2	0	1	0	-1	2		2	0	2	-1	2	2	2	-3	2		2	2	-1	2	0	2	2	-1	0	
MOD	114111896	HJ	1008		TUAPSE	RUS	1	1	1	1	1	1	1	0	0		0	0	0	0	0	0	0	0	0		0	0	0	0	0	0	0	-6	-6	0		0	0	0	0	0	0	0	0	1
MOD	114089413	HN	1026	S	XIUWEN	CHN	2	2	2	2	2	2	2	1	0		-1	2	2	2	-1	2	-2	2	2		2	-1	-1	-8	-1	-1	2	2	2		-2	2	-1	2	2	2	-1	0	1	
ADD	114089420	HN	1170	S	JIAN	CHN	-4	-8	-14	-27	-55	-29	-19	-15	-14		-19	-19	-12	-10	-9	-10	-24	-24	-18		-14	-15	-19	-29	-55	-27	-14	-8	-4		-6	-16	2	8	9	8	2	-16	-6	
MOD	114089407	HN	1224	S	NANNING 1	CHN	5	6	5	6	5	6	5	6	5		5	4	3	0	1	-1	-6	-3	-4		-4	-7	-3	-3	-3	-4	-4	-7	-3		-6	-1	1	0	3	4	5	5	6	
ADD	114089421	HN	1323	S	SHUANGYASHAN 1	CHN	2	2	2	2	2	-6	-6	2	2		2	2	2	2	-15	-15	-9	-8	-8		-8	-8	-8	-12	-8	2	2	2	2		2	2	2	-4	-2	2	2	2	2	

Partie / Part / Parte B

AMS	Id No	JN	Freq	Sync	Site name	Ctry	Geocoords	Pr	Bdw	Power	Emrp	Azm	Ant	Hgt	Cond	Rmks	Coord_A	Coord_B
PLN	075003478	HJ	945	S	NOVOCHERKASSK ROST	RUS	040E02 47N25	9	16	40	16.3		A	55	3			
PLN	075003478	HN	945	S	NOVOCHERKASSK ROST	RUS	040E02 47N25	9	16	40	16.0		B		3			
MOD	114023104	HJ	945	S	NOVOCHERKASSK ROST	RUS	040E02 47N24	9	16	40	16.9		A	125	3	A/138	ROU	
MOD	114023104	HN	945	S	NOVOCHERKASSK ROST	RUS	040E02 47N24	9	16	40	16.9		A	125	3	A/138	ROU	ROU
PLN	075004468	HJ	1071		ILLIZI	ALG	008E26 26N01	0	9	50	17.4		A	70	0.1			
PLN	075004468	HN	1071		ILLIZI	ALG	008E26 26N01	0	9	15	12.0		A	70	0.1			
MOD	114046342	HJ	1071		ILLIZI	ALG	008E29 26N33	0	9	50	17.4		A	70	0.1	A/138		
MOD	114046342	HN	1071		ILLIZI	ALG	008E29 26N33	0	9	15	12.0		A	70	0.1	A/138		
PLN	075006319	HJ	1323		CONSTANTINE	ALG	006E38 36N23	0	9	40	16.4		A	50	3			
PLN	075006319	HN	1323		CONSTANTINE	ALG	006E38 36N23	0	9	20	13.4		A	50	3			
MOD	114034376	HJ	1323		SIDI OKBA	ALG	005E56 34N47	0	9	40	16.4		A	50	3	A/138		
MOD	114034376	HN	1323		SIDI OKBA	ALG	005E56 34N47	0	9	15	12.1		A	50	3	A/138		
ADD	114046345	HJ	1575		ATKARSK	RUS	044E59 51N52	9	16	0.1	-13.0		A	10	3	A/138		
ADD	114046345	HN	1575		ATKARSK	RUS	044E59 51N52	9	16	0.1	-13.0		A	10	3	A/138		

Annex to notifying administration

CHN

Modification to the Plan					Affected assignment in the Plan				Worst affected point	
Freq	Ctry	Site name	Id No	HJ/HN	Ctry	Freq	Site name	Id No	Azm	Eu_Inc
576	CHN	KUNMING 2	114089408	HN	LAO	576	LUANG PRABANG	075000594	240	0.65
	CHN	KUNMING 2	114089408	HN	RUS	576	RADUGA NSB	108059010	0	0.61
603	CHN	ZHENGZHOU 2	114089411	HN	KOR	603	NAM YANG	075000775	280	8.18
	CHN	ZHENGZHOU 2	114089411	HN	MNG	603	BAIANHONGOR	075000778	100	0.86
	CHN	ZHENGZHOU 2	114089411	HN	MNG	603	MUREN	075000779	80	0.58
639	CHN	XINDU	114089417	HN	IND	639	KOHIMA	075001125	80	2.15
	CHN	XINDU	114089417	HN	LAO	639	VIENTIANE	075001132	40	0.68
	CHN	XINDU	114089417	HN	RUS	639	KIRENSK	075001147	240	0.51
738	CHN	XIANGTAN	114089412	HN	J	738	NAHA	075001868	220	0.52
	CHN	XIANGTAN	114089412	HN	LAO	738	PAKSE	075001875	240	1.05
	CHN	XIANGTAN	114089412	HN	PHL	738	VALENZUELA BUL	075001879	260	1.51
	CHN	XIANGTAN	114089412	HN	VTN	738	QUINHON	075001887	0	2.14
756	CHN	HARBIN 1	114089416	HN	J	756	KUMAMOTO	075002055	320	0.83
	CHN	HARBIN 1	114089416	HN	KOR	756	SEOUL	075002056	20	9.65
	CHN	HARBIN 1	114089416	HN	KRE	756	HAMHEUNG	075002057	0	11.73
	CHN	HARBIN 1	114089416	HN	KRE	765	HYESAN	075002113	320	2.64
	CHN	HARBIN 1	114089416	HN	RUS	765	BEREZOVYI Khab	109073593	240	0.52
	CHN	HARBIN 1	114089416	HN	RUS	765	BIKIN Khab	108047112	220	1.59
	CHN	HARBIN 1	114089416	HN	RUS	765	CHEGDOMYN Khab	104067925	180	0.69
	CHN	HARBIN 1	114089416	HN	RUS	765	KOMSOMOLSK NA AMURE Khab	104067923	160	0.57
	CHN	HARBIN 1	114089416	HN	RUS	765	TETUKHE Khab	075002130	260	1.63
	CHN	HARBIN 1	114089416	HN	RUS	765	TROITSKOE Khab	104067924	220	0.80
	CHN	HARBIN 1	114089416	HN	RUS	765	VYSOKOGORNIY Khab	104067930	200	0.59
	CHN	HARBIN 1	114089416	HN	RUS	765	YAGODNIY Khab	104067927	220	0.50
810	CHN	HANGZHOU 1	114089406	HN	KOR	810	DAEGU	075002443	240	5.53
	CHN	HANGZHOU 1	114089406	HN	KRE	810	KAESONG	075002444	200	3.33
	CHN	HANGZHOU 1	114089406	HN	PHL	810	QUEZON CITY	075002451	0	2.77
873	CHN	HARBIN 1	114089418	HN	J	873	KUMAMOTO	075002924	340	2.93
	CHN	HARBIN 1	114089418	HN	KOR	864	GANGNEUNG	075002861	0	0.82
	CHN	HARBIN 1	114089418	HN	KRE	882	WONSAN	075002990	320	0.77
	CHN	HARBIN 1	114089418	HN	RUS	864	BLAGOVESHCHENSK	075002883	180	2.32
	CHN	HARBIN 1	114089418	HN	RUS	873	KHABAROVSK	098000341	200	4.65
	CHN	HARBIN 1	114089418	HN	RUS	882	ZEYA	075003004	160	1.28
927	CHN	KAILI	114089414	HN	RUS	927	TAYSHET	075003302	0	0.58

Annex to notifying administration

CHN

Modification to the Plan					Affected assignment in the Plan				Worst affected point	
Freq	Ctry	Site name	Id No	HJ/HN	Ctry	Freq	Site name	Id No	Azm	Eu_Inc
	CHN	KAILI	114089414	HN	THA	927	BANGKOK	075003298	0	1.96
1026	CHN	XIUWEN	114089413	HN	AUS	1026	PT HEDLAND WA	075004031	60	0.59
	CHN	XIUWEN	114089413	HN	J	1026	NAGO	075004104	140	0.61
	CHN	XIUWEN	114089413	HN	LAO	1026	VIENTIANE	075004109	80	5.52
	CHN	XIUWEN	114089413	HN	PHL	1026	NOVALICHES QC	075004118	240	0.77
	CHN	XIUWEN	114089413	HN	RUS	1026	TOMSK	075004124	40	0.63
	CHN	XIUWEN	114089413	HN	THA	1026	PHITSANULOK	075004121	0	4.38
1116	CHN	HARBIN 1	114089419	HN	RUS	1116	KHABAROVSK	100001079	320	0.54
1170	CHN	JIAN	114089420	HN	PHL	1170	MUNTI RIZAL	075005198	320	14.59
1215	CHN	SHENYANG	114089410	HN	KOR	1215	JAECHEON	075005535	0	0.79
1224	CHN	NANNING 1	114089407	HN	THA	1224	BANGKOK	075005626	40	2.93
	CHN	NANNING 1	114089407	HN	THA	1224	CHIANG RAI	075005627	100	8.60
	CHN	NANNING 1	114089407	HN	THA	1233	UDON THANI	075005696	60	2.94
1323	CHN	SHUANGYASHAN 1	114089421	HN	J	1323	CHIZU	075006354	0	3.93
	CHN	SHUANGYASHAN 1	114089421	HN	J	1323	FUKUSHIMA	075006350	340	5.54
	CHN	SHUANGYASHAN 1	114089421	HN	J	1323	GOZU	075006351	0	3.58
	CHN	SHUANGYASHAN 1	114089421	HN	J	1323	KAMINAKA	075006355	0	2.37
	CHN	SHUANGYASHAN 1	114089421	HN	J	1323	MUIKAICHI	090000438	0	2.64
	CHN	SHUANGYASHAN 1	114089421	HN	J	1323	MUIKAMACHI	075006357	340	5.82
	CHN	SHUANGYASHAN 1	114089421	HN	J	1323	NOMURA	099000005	0	2.02
	CHN	SHUANGYASHAN 1	114089421	HN	J	1323	OCHIAI	075006353	0	3.60
	CHN	SHUANGYASHAN 1	114089421	HN	J	1323	SUSAKI	075006358	20	2.04
	CHN	SHUANGYASHAN 1	114089421	HN	J	1323	TAKETA	075006359	0	1.71
	CHN	SHUANGYASHAN 1	114089421	HN	J	1323	YAMADA	075006360	340	7.49
	CHN	SHUANGYASHAN 1	114089421	HN	KOR	1323	SO SA	075006361	20	5.02
	CHN	SHUANGYASHAN 1	114089421	HN	KOR	1323	ULNEUNGDO	075006362	0	8.00
	CHN	SHUANGYASHAN 1	114089421	HN	KOR	1323	YUNGKWANG	075006363	20	2.13
	CHN	SHUANGYASHAN 1	114089421	HN	KRE	1314	HONGWON	075006292	0	1.04
	CHN	SHUANGYASHAN 1	114089421	HN	KRE	1323	TAECHON	075006364	80	9.76
	CHN	SHUANGYASHAN 1	114089421	HN	KRE	1332	HWAPYONG	075006427	0	2.47
	CHN	SHUANGYASHAN 1	114089421	HN	RUS	1314	BELOGORSK AMUR	110014971	120	0.57
	CHN	SHUANGYASHAN 1	114089421	HN	RUS	1314	KHABAROVSK	107075017	240	6.04
	CHN	SHUANGYASHAN 1	114089421	HN	RUS	1332	VLADIVOSTOK	100003962	320	8.53

Annex to notifying administration

RUS

Modification to the Plan					Affected assignment in the Plan				Worst affected point	
Freq	Ctry	Site name	Id No	HJ/HN	Ctry	Freq	Site name	Id No	Azm	Eu_Inc
918	RUS	ARKHANGELSK KOSKOVO	114112340	HN	SVN	918	LJUBLJANA	075003241	40	0.92

Annex to affected administration

AUS

Modification to the Plan					Affected assignment in the Plan				Worst affected point	
Freq	Ctry	Site name	Id No	HJ/HN	Ctry	Freq	Site name	Id No	Azm	Eu_Inc
1026	CHN	XIUWEN	114089413	HN	AUS	1026	PT HEDLAND WA	075004031	60	0.59

Annex to affected administration

IND

Modification to the Plan					Affected assignment in the Plan				Worst affected point	
Freq	Ctry	Site name	Id No	HJ/HN	Ctry	Freq	Site name	Id No	Azm	Eu_Inc
639	CHN	XINDU	114089417	HN	IND	639	KOHIMA	075001125	80	2.15

Annex to affected administration

J

Modification to the Plan					Affected assignment in the Plan				Worst affected point	
Freq	Ctry	Site name	Id No	HJ/HN	Ctry	Freq	Site name	Id No	Azm	Eu_Inc
738	CHN	XIANGTAN	114089412	HN	J	738	NAHA	075001868	220	0.52
756	CHN	HARBIN 1	114089416	HN	J	756	KUMAMOTO	075002055	320	0.83
873	CHN	HARBIN 1	114089418	HN	J	873	KUMAMOTO	075002924	340	2.93
1026	CHN	XIUWEN	114089413	HN	J	1026	NAGO	075004104	140	0.61
1323	CHN	SHUANGYASHAN 1	114089421	HN	J	1323	CHIZU	075006354	0	3.93
	CHN	SHUANGYASHAN 1	114089421	HN	J	1323	FUKUSHIMA	075006350	340	5.54
	CHN	SHUANGYASHAN 1	114089421	HN	J	1323	GOZU	075006351	0	3.58
	CHN	SHUANGYASHAN 1	114089421	HN	J	1323	KAMINAKA	075006355	0	2.37
	CHN	SHUANGYASHAN 1	114089421	HN	J	1323	MUIKAICHI	090000438	0	2.64
	CHN	SHUANGYASHAN 1	114089421	HN	J	1323	MUIKAMACHI	075006357	340	5.82
	CHN	SHUANGYASHAN 1	114089421	HN	J	1323	NOMURA	099000005	0	2.02
	CHN	SHUANGYASHAN 1	114089421	HN	J	1323	OCHIAI	075006353	0	3.60
	CHN	SHUANGYASHAN 1	114089421	HN	J	1323	SUSAKI	075006358	20	2.04
	CHN	SHUANGYASHAN 1	114089421	HN	J	1323	TAKETA	075006359	0	1.71
	CHN	SHUANGYASHAN 1	114089421	HN	J	1323	YAMADA	075006360	340	7.49

Annex to affected administration

KOR

<i>Modification to the Plan</i>					<i>Affected assignment in the Plan</i>				<i>Worst affected point</i>	
<i>Freq</i>	<i>Ctry</i>	<i>Site name</i>	<i>Id No</i>	<i>HJ/HN</i>	<i>Ctry</i>	<i>Freq</i>	<i>Site name</i>	<i>Id No</i>	<i>Azm</i>	<i>Eu_Inc</i>
603	CHN	ZHENGZHOU 2	114089411	HN	KOR	603	NAM YANG	075000775	280	8.18
756	CHN	HARBIN 1	114089416	HN	KOR	756	SEOUL	075002056	20	9.65
810	CHN	HANGZHOU 1	114089406	HN	KOR	810	DAEGU	075002443	240	5.53
873	CHN	HARBIN 1	114089418	HN	KOR	864	GANGNEUNG	075002861	0	0.82
1215	CHN	SHENYANG	114089410	HN	KOR	1215	JAECHEON	075005535	0	0.79
1323	CHN	SHUANGYASHAN 1	114089421	HN	KOR	1323	SO SA	075006361	20	5.02
	CHN	SHUANGYASHAN 1	114089421	HN	KOR	1323	ULNEUNGDO	075006362	0	8.00
	CHN	SHUANGYASHAN 1	114089421	HN	KOR	1323	YUNGKWANG	075006363	20	2.13

Annex to affected administration

KRE

Modification to the Plan					Affected assignment in the Plan				Worst affected point	
Freq	Ctry	Site name	Id No	HJ/HN	Ctry	Freq	Site name	Id No	Azm	Eu_Inc
756	CHN	HARBIN 1	114089416	HN	KRE	756	HAMHEUNG	075002057	0	11.73
	CHN	HARBIN 1	114089416	HN	KRE	765	HYESAN	075002113	320	2.64
810	CHN	HANGZHOU 1	114089406	HN	KRE	810	KAESONG	075002444	200	3.33
873	CHN	HARBIN 1	114089418	HN	KRE	882	WONSAN	075002990	320	0.77
1323	CHN	SHUANGYASHAN 1	114089421	HN	KRE	1314	HONGWON	075006292	0	1.04
	CHN	SHUANGYASHAN 1	114089421	HN	KRE	1323	TAECHON	075006364	80	9.76
	CHN	SHUANGYASHAN 1	114089421	HN	KRE	1332	HWAPYONG	075006427	0	2.47

Annex to affected administration

LAO

<i>Modification to the Plan</i>					<i>Affected assignment in the Plan</i>				<i>Worst affected point</i>	
<i>Freq</i>	<i>Ctry</i>	<i>Site name</i>	<i>Id No</i>	<i>HJ/HN</i>	<i>Ctry</i>	<i>Freq</i>	<i>Site name</i>	<i>Id No</i>	<i>Azm</i>	<i>Eu_Inc</i>
576	CHN	KUNMING 2	114089408	HN	LAO	576	LUANG PRABANG	075000594	240	0.65
639	CHN	XINDU	114089417	HN	LAO	639	VIENTIANE	075001132	40	0.68
738	CHN	XIANGTAN	114089412	HN	LAO	738	PAKSE	075001875	240	1.05
1026	CHN	XIUWEN	114089413	HN	LAO	1026	VIENTIANE	075004109	80	5.52

Annex to affected administration

MNG

Modification to the Plan					Affected assignment in the Plan				Worst affected point	
Freq	Ctry	Site name	Id No	HJ/HN	Ctry	Freq	Site name	Id No	Azm	Eu_Inc
603	CHN	ZHENGZHOU 2	114089411	HN	MNG	603	BAIANHONGOR	075000778	100	0.86
	CHN	ZHENGZHOU 2	114089411	HN	MNG	603	MUREN	075000779	80	0.58

Annex to affected administration

PHL

Modification to the Plan					Affected assignment in the Plan				Worst affected point	
Freq	Ctry	Site name	Id No	HJ/HN	Ctry	Freq	Site name	Id No	Azm	Eu_Inc
738	CHN	XIANGTAN	114089412	HN	PHL	738	VALENZUELA BUL	075001879	260	1.51
810	CHN	HANGZHOU 1	114089406	HN	PHL	810	QUEZON CITY	075002451	0	2.77
1026	CHN	XIUWEN	114089413	HN	PHL	1026	NOVALICHES QC	075004118	240	0.77
1170	CHN	JIAN	114089420	HN	PHL	1170	MUNTI RIZAL	075005198	320	14.59

Annex to affected administration

RUS

Modification to the Plan					Affected assignment in the Plan				Worst affected point	
Freq	Ctry	Site name	Id No	HJ/HN	Ctry	Freq	Site name	Id No	Azm	Eu_Inc
576	CHN	KUNMING 2	114089408	HN	RUS	576	RADUGA NSB	108059010	0	0.61
639	CHN	XINDU	114089417	HN	RUS	639	KIRENSK	075001147	240	0.51
756	CHN	HARBIN 1	114089416	HN	RUS	765	BEREZOVYI KHAB	109073593	240	0.52
	CHN	HARBIN 1	114089416	HN	RUS	765	BIKIN KHAB	108047112	220	1.59
	CHN	HARBIN 1	114089416	HN	RUS	765	CHEGDOMYN KHAB	104067925	180	0.69
	CHN	HARBIN 1	114089416	HN	RUS	765	KOMSOMOLSK NA AMURE KHAB	104067923	160	0.57
	CHN	HARBIN 1	114089416	HN	RUS	765	TETUKHE KHAB	075002130	260	1.63
	CHN	HARBIN 1	114089416	HN	RUS	765	TROITSKOE KHAB	104067924	220	0.80
	CHN	HARBIN 1	114089416	HN	RUS	765	VYSOKOGORNIY KHAB	104067930	200	0.59
	CHN	HARBIN 1	114089416	HN	RUS	765	YAGODNIY KHAB	104067927	220	0.50
873	CHN	HARBIN 1	114089418	HN	RUS	864	BLAGOVESCHENSK	075002883	180	2.32
	CHN	HARBIN 1	114089418	HN	RUS	873	KHABAROVSK	098000341	200	4.65
	CHN	HARBIN 1	114089418	HN	RUS	882	ZEYA	075003004	160	1.28
927	CHN	KAILI	114089414	HN	RUS	927	TAYSHET	075003302	0	0.58
1026	CHN	XIUWEN	114089413	HN	RUS	1026	TOMSK	075004124	40	0.63
1116	CHN	HARBIN 1	114089419	HN	RUS	1116	KHABAROVSK	100001079	320	0.54
1323	CHN	SHUANGYASHAN 1	114089421	HN	RUS	1314	BELOGORSK AMUR	110014971	120	0.57
	CHN	SHUANGYASHAN 1	114089421	HN	RUS	1314	KHABAROVSK	107075017	240	6.04
	CHN	SHUANGYASHAN 1	114089421	HN	RUS	1332	VLADIVOSTOK	100003962	320	8.53

Annex to affected administration

SVN

Modification to the Plan					Affected assignment in the Plan				Worst affected point	
Freq	Ctry	Site name	Id No	HJ/HN	Ctry	Freq	Site name	Id No	Azm	Eu_Inc
918	RUS	ARKHANGELSK KOSKOVO	114112340	HN	SVN	918	LJUBLJANA	075003241	40	0.92

Annex to affected administration

THA

Modification to the Plan					Affected assignment in the Plan				Worst affected point	
Freq	Ctry	Site name	Id No	HJ/HN	Ctry	Freq	Site name	Id No	Azm	Eu_Inc
927	CHN	KAILI	114089414	HN	THA	927	BANGKOK	075003298	0	1.96
1026	CHN	XIUWEN	114089413	HN	THA	1026	PHITSANULOK	075004121	0	4.38
1224	CHN	NANNING 1	114089407	HN	THA	1224	BANGKOK	075005626	40	2.93
	CHN	NANNING 1	114089407	HN	THA	1224	CHIANG RAI	075005627	100	8.60
	CHN	NANNING 1	114089407	HN	THA	1233	UDON THANI	075005696	60	2.94

Annex to affected administration

VTN

Modification to the Plan					Affected assignment in the Plan				Worst affected point	
Freq	Ctry	Site name	Id No	HJ/HN	Ctry	Freq	Site name	Id No	Azm	Eu_Inc
738	CHN	XIANGTAN	114089412	HN	VTN	738	QUINHON	075001887	0	2.14