



International Telecommunication Union
Radiocommunication Bureau

BR IFIC No / Date
BR IFIC No / Date
BR IFIC No / Fecha

2948 / 15.06.2021

Section Spéciale No
Special Section No
Sección Especial No

GE75/193

Date limite pour la réception des commentaires :
Expiry date for the receipt of comments :
Fecha límite para la recepción de los comentarios :

05.10.2021

	En-têtes des colonnes	Columns headings	Titulos de las columnas
AMS	PLN (Plan) ADD(Addition) MOD(modification) SUP(Suppression)	PLN (Plan) ADD(Addition) MOD(modification) SUP(Suppression)	PLN (Plan) ADD(Adición) MOD(modificación) SUP(Anulación)
Id No	Numéro d'identification du BR	BR identification number	Número de identificación de la BR
JN	Opération : HJ(jour), HN(Nuit)	Operation : HJ (Day-time), HN(Night-time)	Operación : HJ (día) o HN (noche)
Freq	Fréquence assignée, kHz	Assigned frequency, kHz	Frecuencia asignada, kHz
Sync	S pour réseau synchronisé	S for a synchronized network	S para una red sincronizada
Site name	Nom de l'emplacement d'émission	Name of the transmitter site	Nombre del emplazamiento de transmisión
Ctry	Symbole de pays ou zone géographique	Country or geographical zone symbol	Símbolo del país o zona geográfica
Geocoords	Coordonnées géographiques	Geographical coordinates	Coordenadas geográficas
Pr	Rapport de protection canal adjacent	Adjacent channel protection ratio	Relación de protección en canal adyacente
Bdw	Largeur de bande, kHz	Bandwidth, kHz	Anchura de banda, kHz
Power	Puissance de l'onde porteuse, kW	Carrier power, kW	Potencia de la portadora, kW
Emrp	Rayonnement maximal, dB(kW)	Maximum radiation, dB(kW)	Radiación máxima, dB(kW)
Azm	Azimuth de rayonnement maximal	Azimuth of maximum radiation	Acimut de radiación máxima
Ant	Type d'antenne, A ou B	Antenna type, A or B	Tipo de antena, A o B
Hgt	Hauteur de l'antenne, m	Height of antenna, m	Altura de la antena, m
Cond	Conductivité du sol, mS/m	Ground conductivity, mS/m	Conductividad del suelo, mS/m
Rmks	Commentaires du BR	Comments of the BR	Comentarios de la BR
Coord A	Coordination effectuée	Coordination effected	Coordinación efectuada
Coord B	Coordination nécessaire	Coordination required	Coordinación a efectuar

Partie / Part / Parte A

AMS	Id No	JN	Freq	Sync	Site name	Ctry	Geocoords	Pr	Bdw	Power	Emrp	Azm	Ant	Hgt	Cond	Rmks	Coord_A	Coord_B
PLN	075000654	HJ	585		SURABAYA-1	INS	112E44 07S16	9	18	100	22.1		A	256	3			
PLN	075000654	HN	585		SURABAYA-1	INS	112E44 07S16	9	18	100	22.1		A	256	3			
MOD	121058074	HJ	585		Surabaya-1	INS	112E32 07S29	9	18	100	22.1		A	256	10			
MOD	121058074	HN	585		Surabaya-1	INS	112E32 07S29	9	18	100	22.1		A	256	10			AUS
PLN	075001020	HJ	630		UJUNGPANDANG	INS	119E28 05S09	9	18	100	22.1		A	234	3			
PLN	075001020	HN	630		UJUNGPANDANG	INS	119E28 05S09	9	18	100	22.1		A	234	3			
MOD	121058070	HJ	630		Makassar-3	INS	119E25 05S16	9	18	100	22.1		A	234	10			
MOD	121058070	HN	630		Makassar-3	INS	119E25 05S16	9	18	100	22.1		A	234	10			AUS
PLN	075002200	HJ	774		FAKFAK	INS	132E17 02S55	9	18	10	10.4		A	97	1			
PLN	075002200	HN	774		FAKFAK	INS	132E17 02S55	9	18	10	10.4		A	97	1			
MOD	121058065	HJ	774		Fakfak-1	INS	132E21 02S57	9	18	10	11.0		A	97	10			
MOD	121058065	HN	774		Fakfak-1	INS	132E21 02S57	9	18	10	11.0		A	97	10			AUS
PLN	075002438	HJ	810		MERAUKE	INS	140E22 08S30	9	18	5	7.6		A	104	0.3			
PLN	075002438	HN	810		MERAUKE	INS	140E22 08S30	9	18	5	7.6		A	104	0.3			
MOD	121058067	HJ	810		Merauke-1	INS	140E25 08S28	9	18	10	11.0		A	93	10			
MOD	121058067	HN	810		Merauke-1	INS	140E25 08S28	9	18	10	11.0		A	93	10			AUS; PNG
PLN	075002597	HJ	837		ATAMBUA	INS	124E49 09S12	9	18	2	3.4		A	90	0.1			
PLN	075002597	HN	837		ATAMBUA	INS	124E49 09S12	9	18	2	3.4		A	90	0.1			
MOD	121058076	HJ	837		Atambua-1	INS	124E52 09S16	9	18	2	3.4		A	90	10			
MOD	121058076	HN	837		Atambua-1	INS	124E52 09S16	9	18	2	3.4		A	90	10			
PLN	075002809	HJ	855		MEDAN	INS	098E39 03N35	9	18	100	22.1		A	163	1			
PLN	075002809	HN	855		MEDAN	INS	098E39 03N35	9	18	100	22.1		A	163	1			
MOD	121058066	HJ	855		Medan-1	INS	098E25 03N35	9	18	100	22.1		A	163	10			MLA
MOD	121058066	HN	855		Medan-1	INS	098E25 03N35	9	18	100	22.1		A	163	10			
PLN	075003087	HJ	900		SAMARINDA	INS	117E09 00S30	9	18	25	16.1		A	150	3			
PLN	075003087	HN	900		SAMARINDA	INS	117E09 00S30	9	18	25	16.1		A	150	3			
MOD	121058075	HJ	900		Samarinda-3	INS	117E00 00S28	9	18	50	18.0		A	150	10			
MOD	121058075	HN	900		Samarinda-3	INS	117E00 00S28	9	18	50	18.0		A	150	10			AUS; PHL
PLN	075004738	HJ	1107		JOGJAKARTA	INS	110E24 07S48	9	18	10	10.4		A	68	1			
PLN	075004738	HN	1107		JOGJAKARTA	INS	110E24 07S48	9	18	10	10.4		A	68	1			
MOD	121058071	HJ	1107		Yogyakarta-1	INS	110E24 07S46	9	18	10	10.4		A	68	10			
MOD	121058071	HN	1107		Yogyakarta-1	INS	110E24 07S46	9	18	10	10.4		A	68	10			
PLN	075004817	HJ	1116		BIAK	INS	136E04 01S11	9	18	10	10.6		A	100	1			
PLN	075004817	HN	1116		BIAK	INS	136E04 01S11	9	18	10	10.6		A	100	1			
MOD	121058077	HJ	1116		Biak-2	INS	136E04 01S09	9	18	10	10.6		A	100	10			
MOD	121058077	HN	1116		Biak-2	INS	136E04 01S09	9	18	10	10.6		A	100	10			

Partie / Part / Parte A

<u>AMS</u>	<u>Id No</u>	<u>JN</u>	<u>Freq</u>	<u>Sync</u>	<u>Site name</u>	<u>Ctry</u>	<u>Geocoords</u>	<u>Pr</u>	<u>Bdw</u>	<u>Power</u>	<u>Emrp</u>	<u>Azm</u>	<u>Ant</u>	<u>Hgt</u>	<u>Cond</u>	<u>Rmks</u>	<u>Coord_A</u>	<u>Coord_B</u>
PLN	075004926	HJ	1134		BANDJARMASIN	INS	114E33 03S22	9	18	50	19.1		A	132	3			
PLN	075004926	HN	1134		BANDJARMASIN	INS	114E33 03S22	9	18	50	19.1		A	132	3			
MOD	121058064	HJ	1134		Banjarmasin-2	INS	114E42 03S18	9	18	50	19.1		A	132	10			
MOD	121058064	HN	1134		Banjarmasin-2	INS	114E42 03S18	9	18	50	19.1		A	132	10			
PLN	075005340	HJ	1197		PALENGKARAJA	INS	113E11 02S02	9	18	5	7.4		A	63	0.3			
PLN	075005340	HN	1197		PALENGKARAJA	INS	113E11 02S02	9	18	5	7.4		A	63	0.3			
MOD	121058068	HJ	1197		Palangkaraya-1	INS	113E53 02S11	9	18	50	18.0		A	63	10			
MOD	121058068	HN	1197		Palangkaraya-1	INS	113E53 02S11	9	18	50	18.0		A	63	10		AUS; MLA; PHL	
PLN	075005665	HJ	1233		PONTIANAK	INS	109E16 00S05	9	18	50	17.6		A	70	1			
PLN	075005665	HN	1233		PONTIANAK	INS	109E16 00S05	9	18	50	17.6		A	70	1			
MOD	121058069	HJ	1233		Pontianak-1	INS	109E14 00N02	9	18	10	11.0		A	61	10		MLA	
MOD	121058069	HN	1233		Pontianak-1	INS	109E14 00N02	9	18	10	11.0		A	61	10			
PLN	075007116	HJ	1413		PANGKALPINANG	INS	106E09 02S05	9	18	5	7.4		A	53	1			
PLN	075007116	HN	1413		PANGKALPINANG	INS	106E09 02S05	9	18	5	7.4		A	53	1			
MOD	121058072	HJ	1413		Pangkalpinang-1	INS	106E03 01S57	9	18	10	11.0		A	53	10		SNG	
MOD	121058072	HN	1413		Pangkalpinang-1	INS	106E03 01S57	9	18	10	11.0		A	53	10			
PLN	075007500	HJ	1467		TANDJUNGPINANG	INS	104E28 00N55	9	18	10	10.4		A	52	0.3			
PLN	075007500	HN	1467		TANDJUNGPINANG	INS	104E28 00N55	9	18	10	10.4		A	52	0.3			
MOD	121058078	HJ	1467		Tanjungpinang-2	INS	108E22 03N59	9	18	10	11.0		A	51	10			
MOD	121058078	HN	1467		Tanjungpinang-2	INS	108E22 03N59	9	18	10	11.0		A	51	10			
PLN	075007569	HJ	1476		SURAKARTA	INS	110E50 07S32	9	18	50	19.1		A	100	1			
PLN	075007569	HN	1476		SURAKARTA	INS	110E50 07S32	9	18	50	19.1		A	100	1			
MOD	121058073	HJ	1476		Surakarta-1	INS	110E42 07S43	9	18	50	19.1		A	100	10			
MOD	121058073	HN	1476		Surakarta-1	INS	110E42 07S43	9	18	50	19.1		A	100	10			

Annex to notifying administration

INS

Modification to the Plan					Affected assignment in the Plan				Worst affected point	
Freq	Ctry	Site name	Id No	HJ/HN	Ctry	Freq	Site name	Id No	Azm	Eu_Inc
585	INS	Surabaya-1	121058074	HN	AUS	585	KATHERINE NT	075000628	0	2.12
630	INS	Makassar-3	121058070	HN	AUS	630	ALBANY WA	075000922	160	1.83
	INS	Makassar-3	121058070	HN	AUS	630	ROCKHAMPTON QL	075000923	80	2.31
	INS	Makassar-3	121058070	HN	AUS	630	TOWNSVILLE QLD	075000924	40	1.43
774	INS	Fakfak-1	121058065	HN	AUS	774	TOWNSVILLE QLD	075002142	120	0.55
810	INS	Merauke-1	121058067	HN	AUS	810	PERTH WA	075002414	240	1.01
	INS	Merauke-1	121058067	HN	PNG	810	RABAU	075002452	220	0.53
855	INS	Medan-1	121058066	HJ	MLA	864	PENANG	075002863	160	7.73
900	INS	Samarinda-3	121058075	HN	AUS	900	ALICE SPR NT	075003061	340	0.64
	INS	Samarinda-3	121058075	HN	AUS	900	MT TOMPRICE WA	075003065	0	0.83
	INS	Samarinda-3	121058075	HN	PHL	900	BATANGAS BAT	075003108	180	0.52
	INS	Samarinda-3	121058075	HN	PHL	900	DAVAO CITY	075003109	240	1.13
1197	INS	Palangkaraya-1	121058068	HN	AUS	1188	EXMOUTH WA	075005261	20	1.36
	INS	Palangkaraya-1	121058068	HN	AUS	1197	ADELAIDE SA	075005313	300	5.53
	INS	Palangkaraya-1	121058068	HN	MLA	1197	KUDAT	075005362	240	7.57
	INS	Palangkaraya-1	121058068	HN	PHL	1197	BACOLOD CITY	075005367	220	0.70
	INS	Palangkaraya-1	121058068	HN	PHL	1197	DAVAO CITY	075005368	140	0.70
1233	INS	Pontianak-1	121058069	HJ	MLA	1224	JOHORE BAHRU	075005612	100	1.95
1413	INS	Pangkalpinang-1	121058072	HJ	SNG	1422	SINGAPORE 1	075007192	140	6.88

Annex to affected administration

AUS

<i>Modification to the Plan</i>					<i>Affected assignment in the Plan</i>				<i>Worst affected point</i>	
<i>Freq</i>	<i>Ctry</i>	<i>Site name</i>	<i>Id No</i>	<i>HJ/HN</i>	<i>Ctry</i>	<i>Freq</i>	<i>Site name</i>	<i>Id No</i>	<i>Azm</i>	<i>Eu_Inc</i>
585	INS	Surabaya-1	121058074	HN	AUS	585	KATHERINE NT	075000628	0	2.12
630	INS	Makassar-3	121058070	HN	AUS	630	ALBANY WA	075000922	160	1.83
	INS	Makassar-3	121058070	HN	AUS	630	ROCKHAMPTON QL	075000923	80	2.31
	INS	Makassar-3	121058070	HN	AUS	630	TOWNSVILLE QLD	075000924	40	1.43
774	INS	Fakfak-1	121058065	HN	AUS	774	TOWNSVILLE QLD	075002142	120	0.55
810	INS	Merauke-1	121058067	HN	AUS	810	PERTH WA	075002414	240	1.01
900	INS	Samarinda-3	121058075	HN	AUS	900	ALICE SPR NT	075003061	340	0.64
	INS	Samarinda-3	121058075	HN	AUS	900	MT TOMPRICE WA	075003065	0	0.83
1197	INS	Palangkaraya-1	121058068	HN	AUS	1188	EXMOUTH WA	075005261	20	1.36
	INS	Palangkaraya-1	121058068	HN	AUS	1197	ADELAIDE SA	075005313	300	5.53

Annex to affected administration

MLA

<i>Modification to the Plan</i>					<i>Affected assignment in the Plan</i>				<i>Worst affected point</i>	
<i>Freq</i>	<i>Ctry</i>	<i>Site name</i>	<i>Id No</i>	<i>HJ/HN</i>	<i>Ctry</i>	<i>Freq</i>	<i>Site name</i>	<i>Id No</i>	<i>Azm</i>	<i>Eu_Inc</i>
855	INS	Medan-1	121058066	HJ	MLA	864	PENANG	075002863	160	7.73
1197	INS	Palangkaraya-1	121058068	HN	MLA	1197	KUDAT	075005362	240	7.57
1233	INS	Pontianak-1	121058069	HJ	MLA	1224	JOHORE BAHRU	075005612	100	1.95

Annex to affected administration

PHL

<i>Modification to the Plan</i>					<i>Affected assignment in the Plan</i>				<i>Worst affected point</i>	
<i>Freq</i>	<i>Ctry</i>	<i>Site name</i>	<i>Id No</i>	<i>HJ/HN</i>	<i>Ctry</i>	<i>Freq</i>	<i>Site name</i>	<i>Id No</i>	<i>Azm</i>	<i>Eu_Inc</i>
900	INS	Samarinda-3	121058075	HN	PHL	900	BATANGAS BAT	075003108	180	0.52
	INS	Samarinda-3	121058075	HN	PHL	900	DAVAO CITY	075003109	240	1.13
1197	INS	Palangkaraya-1	121058068	HN	PHL	1197	BACOLOD CITY	075005367	220	0.70
	INS	Palangkaraya-1	121058068	HN	PHL	1197	DAVAO CITY	075005368	140	0.70

Annex to affected administration

PNG

Modification to the Plan					Affected assignment in the Plan				Worst affected point	
Freq	Ctry	Site name	Id No	HJ/HN	Ctry	Freq	Site name	Id No	Azm	Eu_Inc
810	INS	Merauke-1	121058067	HN	PNG	810	RABAU	075002452	220	0.53

Annex to affected administration

SNG

Modification to the Plan					Affected assignment in the Plan				Worst affected point	
Freq	Ctry	Site name	Id No	HJ/HN	Ctry	Freq	Site name	Id No	Azm	Eu_Inc
1413	INS	Pangkalpinang-1	121058072	HJ	SNG	1422	SINGAPORE 1	075007192	140	6.88