



International Telecommunication Union
Radiocommunication Bureau

BR IFIC No / Date
BR IFIC No / Date
BR IFIC No / Fecha

2965 / 22.02.2022

Section Spéciale No
Special Section No
Sección Especial No

GE75/197

Date limite pour la réception des commentaires :
Expiry date for the receipt of comments :
Fecha límite para la recepción de los comentarios :

14.06.2022

	En-têtes des colonnes	Columns headings	Titulos de las columnas
AMS	PLN (Plan) ADD(Addition) MOD(modification) SUP(Suppression)	PLN (Plan) ADD(Addition) MOD(modification) SUP(Suppression)	PLN (Plan) ADD(Adición) MOD(modificación) SUP(Anulación)
Id No	Numéro d'identification du BR	BR identification number	Número de identificación de la BR
JN	Opération : HJ(jour), HN(Nuit)	Operation : HJ (Day-time), HN(Night-time)	Operación : HJ (día) o HN (noche)
Freq	Fréquence assignée, kHz	Assigned frequency, kHz	Frecuencia asignada, kHz
Sync	S pour réseau synchronisé	S for a synchronized network	S para una red sincronizada
Site name	Nom de l'emplacement d'émission	Name of the transmitter site	Nombre del emplazamiento de transmisión
Ctry	Symbole de pays ou zone géographique	Country or geographical zone symbol	Símbolo del país o zona geográfica
Geocoords	Coordonnées géographiques	Geographical coordinates	Coordenadas geográficas
Pr	Rapport de protection canal adjacent	Adjacent channel protection ratio	Relación de protección en canal adyacente
Bdw	Largeur de bande, kHz	Bandwidth, kHz	Anchura de banda, kHz
Power	Puissance de l'onde porteuse, kW	Carrier power, kW	Potencia de la portadora, kW
Emrp	Rayonnement maximal, dB(kW)	Maximum radiation, dB(kW)	Radiación máxima, dB(kW)
Azm	Azimuth de rayonnement maximal	Azimuth of maximum radiation	Acimut de radiación máxima
Ant	Type d'antenne, A ou B	Antenna type, A or B	Tipo de antena, A o B
Hgt	Hauteur de l'antenne, m	Height of antenna, m	Altura de la antena, m
Cond	Conductivité du sol, mS/m	Ground conductivity, mS/m	Conductividad del suelo, mS/m
Rmks	Commentaires du BR	Comments of the BR	Comentarios de la BR
Coord A	Coordination effectuée	Coordination effected	Coordinación efectuada
Coord B	Coordination nécessaire	Coordination required	Coordinación a efectuar

Partie / Part / Parte A

<u>AMS</u>	<u>Id No</u>	<u>JN</u>	<u>Freq</u>	<u>Sync</u>	<u>Site name</u>	<u>Ctry</u>	<u>Geocoords</u>	<u>Pr</u>	<u>Bdw</u>	<u>Power</u>	<u>Emrp</u>	<u>Azm</u>	<u>Ant</u>	<u>Hgt</u>	<u>Cond</u>	<u>Rmks</u>	<u>Coord_A</u>	<u>Coord_B</u>
PLN	075000367	HJ	540		BANGKOK	THA	100E31 13N48	9	20	10	10.0		A	50	30			
PLN	075000367	HN	540		BANGKOK	THA	100E31 13N48	9	20	10	10.0		A	50	30			
MOD	121115713	HJ	540		BANGKOK-1	THA	100E31 13N47	9	18	10	10.1		A	60	30			
MOD	121115713	HN	540		BANGKOK-1	THA	100E31 13N47	9	18	10	10.1		A	60	30			
PLN	075000610	HJ	576		BANGKOK	THA	100E33 13N41	9	20	10	10.0		A	35	30			
PLN	075000610	HN	576		BANGKOK	THA	100E33 13N41	9	20	10	10.0		A	35	30			
MOD	121115705	HJ	576		BANGKOK-2	THA	100E34 13N52	9	18	10	10.0		A	48	30			
MOD	121115705	HN	576		BANGKOK-2	THA	100E34 13N52	9	18	10	10.0		A	48	30			
PLN	075001208	HJ	648		PHRAE	THA	100E11 18N15	9	20	50	17.4		A	116	1			
PLN	075001208	HN	648		PHRAE	THA	100E11 18N15	9	20	50	17.4		A	116	1			
MOD	121115719	HJ	585		PHRAE-1	THA	100E11 18N12	9	18	50	17.3		A	116	3			
MOD	121115719	HN	585		PHRAE-1	THA	100E11 18N12	9	18	50	17.3		A	116	3		CHN; VTN	
PLN	075000802	HJ	603		BANGKOK	THA	100E31 13N48	9	20	20	13.4		A	125	30			
PLN	075000802	HN	603		BANGKOK	THA	100E31 13N48	9	20	20	13.4		A	125	30			
MOD	121115715	HJ	594		BANGKOK-3	THA	100E31 13N47	9	18	20	13.4		A	125	30		VTN	
MOD	121115715	HN	594		BANGKOK-3	THA	100E31 13N47	9	18	20	13.4		A	125	30		MLA	
PLN	075001385	HJ	675		CHIANG MAI	THA	099E06 18N54	9	20	20	13.4		A	108	1			
PLN	075001385	HN	675		CHIANG MAI	THA	099E06 18N54	9	20	20	13.4		A	108	1			
MOD	121115695	HJ	612		CHIANG MAI-1	THA	099E02 18N52	9	18	20	13.3		A	112	3			
MOD	121115695	HN	612		CHIANG MAI-1	THA	099E02 18N52	9	18	20	13.3		A	112	3		CHN; IND; MLA; VTN	
PLN	075000854	HJ	612		LOPBURI	THA	100E54 14N53	9	20	20	13.4		A	114	1			
PLN	075000854	HN	612		LOPBURI	THA	100E54 14N53	9	20	20	13.4		A	114	1			
MOD	121115716	HJ	612		LOP BURI-1	THA	100E38 14N52	9	18	20	13.4		A	117	10			
MOD	121115716	HN	612		LOP BURI-1	THA	100E38 14N52	9	18	20	13.4		A	117	10			
PLN	075000912	HJ	621		KHON KAEN	THA	102E49 16N18	9	20	100	23.0	70	B		10			
PLN	075000912	HN	621		KHON KAEN	THA	102E49 16N18	9	20	100	23.0	70	B		10			
MOD	121115699	HJ	621		KHON KAEN-2	THA	102E57 16N28	9	18	100	20.9		A	165	3			
MOD	121115699	HN	621		KHON KAEN-2	THA	102E57 16N28	9	18	100	20.9		A	165	3		IND; MLA	
PLN	075001041	HJ	630		BANGKOK	THA	100E34 13N45	9	20	10	10.0		A	45	30			
PLN	075001041	HN	630		BANGKOK	THA	100E34 13N45	9	20	10	10.0		A	45	30			
MOD	121115717	HJ	630		BANGKOK-4	THA	100E33 13N53	9	18	10	10.1		A	68	30			
MOD	121115717	HN	630		BANGKOK-4	THA	100E33 13N53	9	18	10	10.1		A	68	30			
PLN	075009787	HJ	1584		CHIANG MAI	THA	098E59 18N46	9	20	1	0.0		A	30	1			
PLN	075009787	HN	1584		CHIANG MAI	THA	098E59 18N46	9	20	1	0.0		A	30	1			
MOD	121115702	HJ	639		LAMPHUN-1	THA	099E02 18N34	9	18	10	10.1		A	50	3			
MOD	121115702	HN	639		LAMPHUN-1	THA	099E02 18N34	9	18	10	10.1		A	50	3		CHN	

Partie / Part / Parte A

AMS	Id No	JN	Freq	Sync	Site name	Ctry	Geocoords	Pr	Bdw	Power	Emrp	Azm	Ant	Hgt	Cond	Rmks	Coord_A	Coord_B
PLN	075006599	HJ	1350	S	SURIN	THA	103E30 14N53	9	20	10	10.4		A	56	10			
PLN	075006599	HN	1350	S	SURIN	THA	103E30 14N53	9	20	10	10.4		A	56	10			
MOD	121115752	HJ	666		SURIN-1	THA	103E29 14N52	9	18	10	10.3		A	99	3			
MOD	121115752	HN	666		SURIN-1	THA	103E29 14N52	9	18	10	10.3		A	99	3			MLA
PLN	075001323	HJ	666		UDON THANI	THA	102E48 17N24	9	20	20	13.4		A	108	10			
PLN	075001323	HN	666		UDON THANI	THA	102E48 17N24	9	20	20	13.4		A	108	10			
MOD	121115720	HJ	666		TAK-1	THA	099E09 16N52	9	18	20	13.5		A	120	30			
MOD	121115720	HN	666		TAK-1	THA	099E09 16N52	9	18	20	13.5		A	120	30			MLA
PLN	075009072	HJ	1566		N SITHAMMARAT	THA	099E55 08N30	9	20	50	17.4		A	48	10			
PLN	075009072	HN	1566		N SITHAMMARAT	THA	099E55 08N30	9	20	50	17.4		A	48	10			
MOD	121115769	HJ	684		N SITHAMMARAT-2	THA	099E57 08N29	9	18	50	17.4		A	109	30			IND
MOD	121115769	HN	684		N SITHAMMARAT-2	THA	099E57 08N29	9	18	50	17.4		A	109	30			CHN; IND; INS
PLN	075008880	HJ	1539		UDON THANI	THA	102E46 17N26	9	20	10	10.4		A	40	10			
PLN	075008880	HN	1539		UDON THANI	THA	102E46 17N26	9	20	10	10.4		A	40	10			
MOD	121115767	HJ	684		UDON THANI-1	THA	102E49 17N21	9	18	10	10.1		A	72	3			
MOD	121115767	HN	684		UDON THANI-1	THA	102E49 17N21	9	18	10	10.1		A	72	3			CHN; IND
PLN	075001506	HJ	693		SARABURI	THA	100E55 14N31	9	20	20	13.4		A	108	1			
PLN	075001506	HN	693		SARABURI	THA	100E55 14N31	9	20	20	13.4		A	108	1			
MOD	121115721	HJ	693		SARABURI-1	THA	100E54 14N30	9	18	20	13.4		A	108	10			
MOD	121115721	HN	693		SARABURI-1	THA	100E54 14N30	9	18	20	13.4		A	108	10			
PLN	075001624	HJ	711	S	CHIANG MAI	THA	098E59 18N51	9	20	20	13.4		A	102	1			
PLN	075001624	HN	711	S	CHIANG MAI	THA	098E59 18N51	9	20	20	13.4		A	102	1			
MOD	121115694	HJ	711		CHIANG MAI-2	THA	098E58 18N51	9	18	5	7.4		A	105	3			
MOD	121115694	HN	711		CHIANG MAI-2	THA	098E58 18N51	9	18	5	7.4		A	105	3			
PLN	075002274	HJ	783		LOPBURI	THA	100E42 14N53	9	20	20	13.4		A	96	1			
PLN	075002274	HN	783		LOPBURI	THA	100E42 14N53	9	20	20	13.4		A	96	1			
MOD	121115727	HJ	711		LOP BURI-2	THA	100E38 14N52	9	18	20	13.3		A	96	10			
MOD	121115727	HN	711		LOP BURI-2	THA	100E38 14N52	9	18	20	13.3		A	96	10			
PLN	075001883	HJ	738		CHIANG MAI	THA	098E56 18N18	9	20	10	10.4		A	104	1			
PLN	075001883	HN	738		CHIANG MAI	THA	098E56 18N18	9	20	10	10.4		A	104	1			
MOD	121115723	HJ	738		CHIANG MAI-3	THA	099E00 18N46	9	18	10	10.4		A	104	3			
MOD	121115723	HN	738		CHIANG MAI-3	THA	099E00 18N46	9	18	10	10.4		A	104	3			
PLN	075001937	HJ	747		SONGKHLA	THA	100E36 07N10	9	20	10	10.4		A	104	10			
PLN	075001937	HN	747		SONGKHLA	THA	100E36 07N10	9	20	10	10.4		A	104	10			
MOD	121115725	HJ	738		SONGKHLA-2	THA	100E30 07N02	9	18	10	10.4		A	104	30			CBG; IND
MOD	121115725	HN	738		SONGKHLA-2	THA	100E30 07N02	9	18	10	10.4		A	104	30			INS

Partie / Part / Parte A

<u>AMS</u>	<u>Id No</u>	<u>JN</u>	<u>Freq</u>	<u>Sync</u>	<u>Site name</u>	<u>Ctry</u>	<u>Geocoords</u>	<u>Pr</u>	<u>Bdw</u>	<u>Power</u>	<u>Emrp</u>	<u>Azm</u>	<u>Ant</u>	<u>Hgt</u>	<u>Cond</u>	<u>Rmks</u>	<u>Coord_A</u>	<u>Coord_B</u>
PLN	075001884	HJ	738		BANGKOK	THA	100E30 13N45	9	20	20	13.4		A	66	30			
PLN	075001884	HN	738		BANGKOK	THA	100E30 13N45	9	20	20	13.4		A	66	30			
MOD	121115724	HJ	747		BANGKOK-7	THA	100E29 13N44	9	18	20	13.4		A	96	30			
MOD	121115724	HN	747		BANGKOK-7	THA	100E29 13N44	9	18	20	13.4		A	96	30		CHN; INS	
PLN	075003663	HJ	972		UDON THANI	THA	102E48 17N22	9	20	50	17.4		A	75	10			
PLN	075003663	HN	972		UDON THANI	THA	102E48 17N22	9	20	50	17.4		A	75	10			
MOD	121115734	HJ	747		UDON THANI-2	THA	102E53 17N16	9	18	50	17.3		A	91	3			
MOD	121115734	HN	747		UDON THANI-2	THA	102E53 17N16	9	18	50	17.3		A	91	3		CHN; INS	
PLN	099051365	HJ	756		Bouchaoui	ALG	002E56 36N44	0	9	10	10.0		A	50	3			
PLN	099051365	HN	756		Bouchaoui	ALG	002E56 36N44	0	9	5	7.0		A	50	3			
MOD	121116766	HJ	756		Aboudid-2	ALG	004E13 36N37	5	9	1000	30.0		A	99	1			
MOD	121116766	HN	756		Aboudid-2	ALG	004E13 36N37	5	9	8.6	9.3		A	99	1			
PLN	075002570	HJ	828		RAYONG	THA	101E17 12N43	9	20	20	13.4		A	87	10			
PLN	075002570	HN	828		RAYONG	THA	101E17 12N43	9	20	20	13.4		A	87	10			
MOD	121115730	HJ	774		RAYONG-1	THA	101E16 12N43	9	18	20	13.7		A	120	3			
MOD	121115730	HN	774		RAYONG-1	THA	101E16 12N43	9	18	20	13.7		A	120	3		MLA	
PLN	075002217	HJ	774		UDON THANI	THA	102E47 17N24	9	20	10	10.0		A	35	10			
PLN	075002217	HN	774		UDON THANI	THA	102E47 17N24	9	20	10	10.0		A	35	10			
MOD	121115706	HJ	774		UDON THANI-3	THA	102E47 17N26	9	18	10	10.7		A	120	3			
MOD	121115706	HN	774		UDON THANI-3	THA	102E47 17N26	9	18	10	10.7		A	120	3			
PLN	089005456	HJ	1413		TAK	THA	099E08 16N53	9	20	10	10.4		A	52	1			
PLN	089005456	HN	1413		TAK	THA	099E08 16N53	9	20	10	10.4		A	52	1			
MOD	121115773	HJ	783		KAMPHAENG PHET-1	THA	099E30 16N28	9	18	10	10.4		A	100	30			
MOD	121115773	HN	783		KAMPHAENG PHET-1	THA	099E30 16N28	9	18	10	10.4		A	100	30		CHN; VTN	
PLN	075009991	HJ	1593		RANONG	THA	098E06 09N09	9	20	10	10.4		A	44	10			
PLN	075009991	HN	1593		RANONG	THA	098E06 09N09	9	20	10	10.4		A	44	10			
MOD	121115704	HJ	783		RANONG-1	THA	098E37 09N54	9	18	10	10.7		A	120	30		VTN	
MOD	121115704	HN	783		RANONG-1	THA	098E37 09N54	9	18	10	10.7		A	120	30			
PLN	075001623	HJ	711	S	BANGKOK	THA	100E36 13N41	9	20	20	13.4		A	102	30			
PLN	075001623	HN	711	S	BANGKOK	THA	100E36 13N41	9	20	20	13.4		A	102	30			
MOD	121115693	HJ	792		BANGKOK-8	THA	100E36 13N41	9	18	5	7.4		A	95	30			
MOD	121115693	HN	792		BANGKOK-8	THA	100E36 13N41	9	18	5	7.4		A	95	30		SNG	
PLN	075004368	HJ	1053		NAKHON SAWAN	THA	100E07 15N38	9	20	10	10.4		A	68	30			
PLN	075004368	HN	1053		NAKHON SAWAN	THA	100E07 15N38	9	20	10	10.4		A	68	30			
MOD	121115735	HJ	801		NAKHON SAWAN-1	THA	100E07 15N40	9	18	10	10.3		A	86	30			
MOD	121115735	HN	801		NAKHON SAWAN-1	THA	100E07 15N40	9	18	10	10.3		A	86	30			

Partie / Part / Parte A

AMS	Id No	JN	Freq	Sync	Site name	Ctry	Geocoords	Pr	Bdw	Power	Emrp	Azm	Ant	Hgt	Cond	Rmks	Coord_A	Coord_B
ADD	121115533	HJ	819		TAM	ALG	005E33 22N49	0	9	1000	30.0		A	92	1			
ADD	121115533	HN	819		TAM	ALG	005E33 22N49	0	9	30	14.8		A	92	1			
PLN	075006042	HJ	1287	S	N SITHAMMARAT	THA	099E48 08N10	9	20	10	10.4		A	58	10			
PLN	075006042	HN	1287	S	N SITHAMMARAT	THA	099E48 08N10	9	20	10	10.4		A	58	10			
MOD	121115749	HJ	828		N SITHAMMARAT-3	THA	099E39 08N02	9	18	10	10.4		A	87	30		MLA; VTN	
MOD	121115749	HN	828		N SITHAMMARAT-3	THA	099E39 08N02	9	18	10	10.4		A	87	30		SNG	
PLN	075002076	HJ	756		PHUKET	THA	098E24 07N58	9	20	50	17.4		A	100	10			
PLN	075002076	HN	756		PHUKET	THA	098E24 07N58	9	20	50	17.4		A	100	10			
MOD	121115726	HJ	828		SUKHOTHAI-1	THA	099E48 17N01	9	18	50	17.5		A	100	30		CHN; VTN	
MOD	121115726	HN	828		SUKHOTHAI-1	THA	099E48 17N01	9	18	50	17.5		A	100	30		CHN; IND; SNG; VTN	
PLN	075002577	HJ	837		BECHAR	ALG	002W15 31N36	0	9	600	27.8		A	90	1			
PLN	075002577	HN	837		BECHAR	ALG	002W15 31N36	0	9	20	12.6		A	90	1			
MOD	122000081	HJ	837		Metlili Chaamba	ALG	003E40 32N17	0	9	1000	30.0		A	90	1			
MOD	122000081	HN	837		Metlili Chaamba	ALG	003E40 32N17	0	9	13.8	11.4		A	90	1			
PLN	075000671	HJ	585		PRACHINBURI	THA	101E25 14N05	9	20	20	13.4		A	117	10			
PLN	075000671	HN	585		PRACHINBURI	THA	101E25 14N05	9	20	20	13.4		A	117	10			
MOD	121115714	HJ	855		PRACHIN BURI-1	THA	101E22 14N04	9	18	20	14.0		A	125	10			
MOD	121115714	HN	855		PRACHIN BURI-1	THA	101E22 14N04	9	18	20	14.0		A	125	10		CHN; INS	
PLN	075009789	HJ	1584		PHUKET	THA	098E23 07N51	9	20	1	0.0		A	47	10			
PLN	075009789	HN	1584		PHUKET	THA	098E23 07N51	9	20	1	0.0		A	47	10			
MOD	121115703	HJ	909		LOEI-1	THA	101E08 17N16	9	18	10	10.4		A	80	10			
MOD	121115703	HN	909		LOEI-1	THA	101E08 17N16	9	18	10	10.4		A	80	10		CHN	
PLN	075003234	HJ	918		CHIANG MAI	THA	098E58 18N48	9	20	10	10.4		A	60	1			
PLN	075003234	HN	918		CHIANG MAI	THA	098E58 18N48	9	20	10	10.4		A	60	1			
MOD	121115707	HJ	918		CHIANG MAI-4	THA	098E56 18N54	9	18	10	10.4		A	82	3			
MOD	121115707	HN	918		CHIANG MAI-4	THA	098E56 18N54	9	18	10	10.4		A	82	3			
PLN	075003361	HJ	936		PATTANI	THA	101E15 06N50	9	20	1.5	2.2		A	45	10			
PLN	075003361	HN	936		PATTANI	THA	101E15 06N50	9	20	1.5	2.2		A	45	10			
MOD	121115731	HJ	936		PATTANI-1	THA	101E08 06N47	9	18	8	9.4		A	73	30		MLA	
MOD	121115731	HN	936		PATTANI-1	THA	101E08 06N47	9	18	8	9.4		A	73	30		INS	
PLN	075000213	HJ	531		KHON KAEN	THA	102E49 16N27	9	20	50	17.4		A	88	10			
PLN	075000213	HN	531		KHON KAEN	THA	102E49 16N27	9	20	50	17.4		A	88	10			
MOD	121115712	HJ	945		KALASIN-1	THA	103E30 16N25	9	18	50	17.5		A	88	3			
MOD	121115712	HN	945		KALASIN-1	THA	103E30 16N25	9	18	50	17.5		A	88	3		CHN; MLA	
PLN	075002336	HJ	792		BANGKOK	THA	100E31 13N48	9	20	20	13.4		A	60	30			
PLN	075002336	HN	792		BANGKOK	THA	100E31 13N48	9	20	20	13.4		A	60	30			

Partie / Part / Parte A

AMS	Id No	JN	Freq	Sync	Site name	Ctry	Geocoords	Pr	Bdw	Power	Emrp	Azm	Ant	Hgt	Cond	Rmks	Coord_A	Coord_B
MOD	121115728	HJ	963		BANGKOK-13	THA	100E31 13N47	9	18	20	13.4		A	78	30			
MOD	121115728	HN	963		BANGKOK-13	THA	100E31 13N47	9	18	20	13.4		A	78	30		BGD; MLA	
PLN	075003851	HJ	990		N RATCHASIMA	THA	102E05 14N58	9	20	10	10.4		A	79	30			
PLN	075003851	HN	990		N RATCHASIMA	THA	102E05 14N58	9	20	10	10.4		A	79	30			
MOD	121115708	HJ	990		NAKHON RATCHASIMA-2	THA	102E08 15N02	9	18	10	10.8		A	100	10			
MOD	121115708	HN	990		NAKHON RATCHASIMA-2	THA	102E08 15N02	9	18	10	10.8		A	100	10			
PLN	075010602	HJ	1602		CHIANG MAI	THA	098E58 18N48	9	20	1	0.0		A	47	1			
PLN	075010602	HN	1602		CHIANG MAI	THA	098E58 18N48	9	20	1	0.0		A	47	1			
MOD	121115771	HJ	999		CHIANG RAI-2	THA	099E48 19N54	9	18	8	9.4		A	75	3			
MOD	121115771	HN	999		CHIANG RAI-2	THA	099E48 19N54	9	18	8	9.4		A	75	3		CHN	
PLN	075003607	HJ	963		N RATCHASIMA	THA	102E07 14N57	9	20	10	10.4		A	77	30			
PLN	075003607	HN	963		N RATCHASIMA	THA	102E07 14N57	9	20	10	10.4		A	77	30			
MOD	121115733	HJ	1008		NAKHON RATCHASIMA-3	THA	102E05 14N57	9	18	10	10.4		A	72	10			
MOD	121115733	HN	1008		NAKHON RATCHASIMA-3	THA	102E05 14N57	9	18	10	10.4		A	72	10		MLA	
PLN	075004369	HJ	1053		N SITHAMMARAT	THA	099E57 08N29	9	20	10	10.4		A	48	10			
PLN	075004369	HN	1053		N SITHAMMARAT	THA	099E57 08N29	9	20	10	10.4		A	48	10			
MOD	121115736	HJ	1044		N SITHAMMARAT-4	THA	099E57 08N29	9	18	10	11.1		A	109	30			
MOD	121115736	HN	1044		N SITHAMMARAT-4	THA	099E57 08N29	9	18	10	11.1		A	109	30		INS; MLA	
PLN	075004458	HJ	1062		BANGKOK	THA	100E34 13N45	9	20	20	13.4		A	72	30			
PLN	075004458	HN	1062		BANGKOK	THA	100E34 13N45	9	20	20	13.4		A	72	30			
MOD	121115737	HJ	1053		BANGKOK-16	THA	100E33 13N53	9	18	10	10.2		A	52	30			
MOD	121115737	HN	1053		BANGKOK-16	THA	100E33 13N53	9	18	10	10.2		A	52	30		CHN; MLA	
PLN	075009990	HJ	1593		LAMPHUN	THA	099E00 18N26	9	20	50	17.4		A	47	1			
PLN	075009990	HN	1593		LAMPHUN	THA	099E00 18N26	9	20	50	17.4		A	47	1			
MOD	121115770	HJ	1053		LAMPANG-2	THA	099E31 18N17	9	18	50	17.2		A	60	3			
MOD	121115770	HN	1053		LAMPANG-2	THA	099E31 18N17	9	18	50	17.2		A	60	3		BGD; CHN; IND; MLA	
PLN	075006041	HJ	1287	S	CHIANG RAI	THA	099E48 19N54	9	20	10	10.4		A	58	1			
PLN	075006041	HN	1287	S	CHIANG RAI	THA	099E48 19N54	9	20	10	10.4		A	58	1			
MOD	121115748	HJ	1080		CHIANG RAI-3	THA	099E48 19N54	9	18	10	10.3		A	63	3			
MOD	121115748	HN	1080		CHIANG RAI-3	THA	099E48 19N54	9	18	10	10.3		A	63	3			
PLN	075004565	HJ	1080	S	YALA	THA	101E10 06N48	9	20	10	10.4		A	69	10			
PLN	075004565	HN	1080	S	YALA	THA	101E10 06N48	9	20	10	10.4		A	69	10			
MOD	121115739	HJ	1080		YALA-3	THA	101E16 06N32	9	18	10	10.4		A	69	30		MLA	
MOD	121115739	HN	1080		YALA-3	THA	101E16 06N32	9	18	10	10.4		A	69	30			
PLN	075004681	HJ	1098		SONGKHLA	THA	100E30 07N00	9	20	10	10.4		A	66	10			
PLN	075004681	HN	1098		SONGKHLA	THA	100E30 07N00	9	20	10	10.4		A	66	10			

Partie / Part / Parte A

AMS	Id No	JN	Freq	Sync	Site name	Ctry	Geocoords	Pr	Bdw	Power	Emrp	Azm	Ant	Hgt	Cond	Rmks	Coord_A	Coord_B
MOD	121115709	HJ	1098		SONGKHLA-3	THA	100E28 06N57	9	18	10	10.4		A	66	30		MLA	
MOD	121115709	HN	1098		SONGKHLA-3	THA	100E28 06N57	9	18	10	10.4		A	66	30			
PLN	075002455	HJ	810	S	KHON KAEN	THA	102E51 16N28	9	20	7	8.9		A	60	10			
PLN	075002455	HN	810	S	KHON KAEN	THA	102E51 16N28	9	20	7	8.9		A	60	10			
MOD	121115729	HJ	1107		KHON KAEN-5	THA	102E50 16N27	9	18	10	10.6		A	81	3			
MOD	121115729	HN	1107		KHON KAEN-5	THA	102E50 16N27	9	18	10	10.6		A	81	3			MLA
PLN	075004836	HJ	1116		SAMUT SAKHON	THA	100E20 13N40	9	20	20	13.4		A	67	30			
PLN	075004836	HN	1116		SAMUT SAKHON	THA	100E20 13N40	9	20	20	13.4		A	67	30			
MOD	121115696	HJ	1107		SAMUT SAKHON-1	THA	100E19 13N40	9	18	20	14.3		A	110	30			
MOD	121115696	HN	1107		SAMUT SAKHON-1	THA	100E19 13N40	9	18	20	14.3		A	110	30			MLA
PLN	075008274	HJ	1485		SURAT THANI	THA	099E18 09N07	9	20	1	0.0		A	30	10			
PLN	075008274	HN	1485		SURAT THANI	THA	099E18 09N07	9	20	1	0.0		A	30	10			
MOD	121115759	HJ	1116		PHITSANULOK-3	THA	100E17 16N48	9	18	8	10.7		A	120	30			
MOD	121115759	HN	1116		PHITSANULOK-3	THA	100E17 16N48	9	18	8	10.7		A	120	30			CHN
PLN	075008279	HJ	1485		N RATCHASIMA	THA	102E00 14N56	9	20	1	0.0		A	50	30			
PLN	075008279	HN	1485		N RATCHASIMA	THA	102E00 14N56	9	20	1	0.0		A	50	30			
MOD	121115763	HJ	1134		NAKHON RATCHASIMA-4	THA	102E06 14N58	9	18	8	9.4		A	66	10			
MOD	121115763	HN	1134		NAKHON RATCHASIMA-4	THA	102E06 14N58	9	18	8	9.4		A	66	10			
PLN	075005061	HJ	1152		CHIANG MAI	THA	098E57 18N42	9	20	20	13.4		A	65	1			
PLN	075005061	HN	1152		CHIANG MAI	THA	098E57 18N42	9	20	20	13.4		A	65	1			
MOD	121115740	HJ	1152		CHIANG MAI-5	THA	098E58 18N49	9	18	20	13.4		A	65	3			
MOD	121115740	HN	1152		CHIANG MAI-5	THA	098E58 18N49	9	18	20	13.4		A	65	3			
PLN	075005062	HJ	1152		KHON KAEN	THA	102E48 16N50	9	20	20	13.4		A	50	10			
PLN	075005062	HN	1152		KHON KAEN	THA	102E48 16N50	9	20	10	10.4		A	50	10			
MOD	121115741	HJ	1152		KHON KAEN-6	THA	102E50 16N27	9	18	20	13.3		A	61	3			
MOD	121115741	HN	1152		KHON KAEN-6	THA	102E50 16N27	9	18	10	10.3		A	61	3			
PLN	075005206	HJ	1170		BANGKOK	THA	100E35 13N48	9	20	20	13.4		A	65	30			
PLN	075005206	HN	1170		BANGKOK	THA	100E35 13N48	9	20	20	13.4		A	65	30			
MOD	121115710	HJ	1179		BANGKOK-20	THA	100E35 13N48	9	18	20	13.5		A	68	30			
MOD	121115710	HN	1179		BANGKOK-20	THA	100E35 13N48	9	18	20	13.5		A	68	30			INS
PLN	075007402	HJ	1449		NARATHIWAT	THA	101E48 06N25	9	20	10	10.6		A	75	10			
PLN	075007402	HN	1449		NARATHIWAT	THA	101E48 06N25	9	20	10	10.6		A	75	10			
MOD	121115758	HJ	1188		PHITSANULOK-5	THA	100E17 16N47	9	18	10	10.4		A	63	30			
MOD	121115758	HN	1188		PHITSANULOK-5	THA	100E17 16N47	9	18	10	10.4		A	63	30			CHN; MLA
PLN	075001145	HJ	639		PRACHINBURI	THA	101E22 14N02	9	20	50	17.6		A	156	10			
PLN	075001145	HN	639		PRACHINBURI	THA	101E22 14N02	9	20	50	17.6		A	156	10			

Partie / Part / Parte A

AMS	Id No	JN	Freq	Sync	Site name	Ctry	Geocoords	Pr	Bdw	Power	Emrp	Azm	Ant	Hgt	Cond	Rmks	Coord_A	Coord_B
MOD	121115718	HJ	1188		SA KAE0-1	THA	102E09 13N47	9	18	50	19.5		A	156	3			
MOD	121115718	HN	1188		SA KAE0-1	THA	102E09 13N47	9	18	50	19.5		A	156	3			AUS; CHN; MLA
PLN	075005304	HJ	1188		SAKON NAKHON	THA	104E10 17N15	9	20	20	13.4		A	63	10			
PLN	075005304	HN	1188		SAKON NAKHON	THA	104E10 17N15	9	20	20	13.4		A	63	10			
MOD	121115744	HJ	1188		SAKON NAKHON-2	THA	104E07 17N09	9	18	20	13.4		A	63	3			
MOD	121115744	HN	1188		SAKON NAKHON-2	THA	104E07 17N09	9	18	20	13.4		A	63	3			
PLN	075001573	HJ	702		LOPBURI	THA	100E49 14N46	9	20	10	10.4		A	107	1			
PLN	075001573	HN	702		LOPBURI	THA	100E49 14N46	9	20	10	10.4		A	107	1			
MOD	121115722	HJ	1197		LOP BURI-4	THA	100E38 14N48	9	18	10	11.3		A	100	10			
MOD	121115722	HN	1197		LOP BURI-4	THA	100E38 14N48	9	18	10	11.3		A	100	10			CHN
PLN	075008276	HJ	1485		CHUMPHON	THA	099E12 10N36	9	20	1	0.0		A	50	10			
PLN	075008276	HN	1485		CHUMPHON	THA	099E12 10N36	9	20	1	0.0		A	50	10			
MOD	121115761	HJ	1206		P KHIRI KHAN-2	THA	099E54 12N23	9	18	8	10.9		A	120	30			
MOD	121115761	HN	1206		P KHIRI KHAN-2	THA	099E54 12N23	9	18	8	10.9		A	120	30			
PLN	075007137	HJ	1413		UBON	THA	104E50 15N15	9	20	10	10.4		A	30	3			
PLN	075007137	HN	1413		UBON	THA	104E50 15N15	9	20	10	10.4		A	30	3			
MOD	121115755	HJ	1215		UBON RATCHATHANI-4	THA	104E52 15N12	9	18	10	10.4		A	60	1			
MOD	121115755	HN	1215		UBON RATCHATHANI-4	THA	104E52 15N12	9	18	10	10.4		A	60	1			CHN
ADD	121131683	HJ	1233		PALERMO	I	013E21 38N09	0	9	0.5	-3.0		A	40	1			
ADD	121131683	HN	1233		PALERMO	I	013E21 38N09	0	9	0.5	-3.0		A	40	1			
PLN	075005696	HJ	1233		UDON THANI	THA	102E47 17N23	9	20	10	10.4		A	60	10			
PLN	075005696	HN	1233		UDON THANI	THA	102E47 17N23	9	20	10	10.4		A	60	10			
MOD	121115746	HJ	1233		UDON THANI-5	THA	102E48 17N22	9	18	10	10.4		A	60	3			
MOD	121115746	HN	1233		UDON THANI-5	THA	102E48 17N22	9	18	10	10.4		A	60	3			
ADD	121131677	HJ	1242		POVEGLIANO	I	012E11 45N46	0	9	0.5	-3.0		A	50	1			
ADD	121131677	HN	1242		POVEGLIANO	I	012E11 45N46	0	9	0.5	-3.0		A	50	1			
PLN	075005628	HJ	1224	S	SURAT THANI	THA	099E10 09N09	9	20	10	10.4		A	55	10			
PLN	075005628	HN	1224	S	SURAT THANI	THA	099E10 09N09	9	20	10	10.4		A	55	10			
MOD	121115745	HJ	1242		PHETCHABUN-3	THA	101E15 16N48	9	18	10	12.0		A	120	10			
MOD	121115745	HN	1242		PHETCHABUN-3	THA	101E15 16N48	9	18	10	12.0		A	120	10			CBG; CHN
PLN	075005992	HJ	1278		BANGKOK	THA	100E30 14N45	9	20	20	13.4		A	60	30			
PLN	075005992	HN	1278		BANGKOK	THA	100E30 14N45	9	20	20	13.4		A	60	30			
MOD	121115747	HJ	1269		BANGKOK-23	THA	100E31 13N47	9	18	20	15.1		A	120	30			
MOD	121115747	HN	1269		BANGKOK-23	THA	100E31 13N47	9	18	20	15.1		A	120	30			IND; INS
PLN	075005922	HJ	1269		SONGKHLA	THA	100E31 07N07	9	20	20	13.4		A	56	10			
PLN	075005922	HN	1269		SONGKHLA	THA	100E31 07N07	9	20	20	13.4		A	56	10			

Partie / Part / Parte A

AMS	Id No	JN	Freq	Sync	Site name	Ctry	Geocoords	Pr	Bdw	Power	Emrp	Azm	Ant	Hgt	Cond	Rmks	Coord_A	Coord_B
MOD	121115697	HJ	1269		SONGKHLA-4	THA	100E34 07N06	9	18	20	14.6		A	104	30			MLA
MOD	121115697	HN	1269		SONGKHLA-4	THA	100E34 07N06	9	18	20	14.6		A	104	30			IND; INS
PLN	075003606	HJ	963		PHUKET	THA	098E23 07N51	9	20	25	14.4		A	78	10			
PLN	075003606	HN	963		PHUKET	THA	098E23 07N51	9	20	25	14.4		A	78	10			
MOD	121115732	HJ	1287		UTTARADIT-1	THA	100E08 17N39	9	18	25	15.5		A	100	30			
MOD	121115732	HN	1287		UTTARADIT-1	THA	100E08 17N39	9	18	25	15.5		A	100	30			BGD; CHN; INS
PLN	075006225	HJ	1305		BANGKOK	THA	100E31 13N47	9	20	10	10.4		A	50	30			
PLN	075006225	HN	1305		BANGKOK	THA	100E31 13N47	9	20	10	10.4		A	50	30			
MOD	121115750	HJ	1305		SARABURI-3	THA	100E54 14N31	9	18	10	12.1		A	120	30			
MOD	121115750	HN	1305		SARABURI-3	THA	100E54 14N31	9	18	10	12.1		A	120	30			CHN
PLN	075006311	HJ	1314		KHON KAEN	THA	102E49 16N26	9	20	20	13.4		A	56	10			
PLN	075006311	HN	1314		KHON KAEN	THA	102E49 16N26	9	20	20	13.4		A	56	10			
MOD	121115698	HJ	1314		KHON KAEN-7	THA	102E48 16N26	9	18	20	14.8		A	108	3			
MOD	121115698	HN	1314		KHON KAEN-7	THA	102E48 16N26	9	18	20	14.8		A	108	3			MLA
PLN	075006598	HJ	1350	S	LAMPANG	THA	099E31 18N17	9	20	10	10.4		A	53	1			
PLN	075006598	HN	1350	S	LAMPANG	THA	099E31 18N17	9	20	10	10.4		A	53	1			
MOD	121115751	HJ	1350		LAMPANG-4	THA	099E31 18N17	9	18	10	10.5		A	63	3			
MOD	121115751	HN	1350		LAMPANG-4	THA	099E31 18N17	9	18	10	10.5		A	63	3			
PLN	075006600	HJ	1350	S	TRANG	THA	099E52 07N40	9	20	10	10.4		A	56	10			
PLN	075006600	HN	1350	S	TRANG	THA	099E52 07N40	9	20	10	10.4		A	56	10			
MOD	121115753	HJ	1350		TRANG-2	THA	099E37 07N31	9	18	10	10.4		A	56	30			
MOD	121115753	HN	1350		TRANG-2	THA	099E37 07N31	9	18	10	10.4		A	56	30			
PLN	075008277	HJ	1485		KHON KAEN	THA	102E49 16N27	9	20	1	0.0		A	50	10			
PLN	075008277	HN	1485		KHON KAEN	THA	102E49 16N27	9	20	1	0.0		A	50	10			
MOD	121115762	HJ	1359		SAKON NAKHON-3	THA	104E06 17N11	9	18	8	9.4		A	55	3			
MOD	121115762	HN	1359		SAKON NAKHON-3	THA	104E06 17N11	9	18	8	9.4		A	55	3			CHN
ADD	121131679	HJ	1377		GORIZIA	I	013E35 45N56	0	9	0.5	-3.0		A	40	1			HRV
ADD	121131679	HN	1377		GORIZIA	I	013E35 45N56	0	9	0.5	-3.0		A	40	1			
PLN	075005063	HJ	1152		SONGKHLA	THA	100E27 07N02	9	20	1	0.4		A	65	10			
PLN	075005063	HN	1152		SONGKHLA	THA	100E27 07N02	9	20	1	0.4		A	65	10			
MOD	121115700	HJ	1404		SONGKHLA-5	THA	100E34 07N08	9	18	50	18.2		A	86	30			
MOD	121115700	HN	1404		SONGKHLA-5	THA	100E34 07N08	9	18	50	18.2		A	86	30			AUS; IND; INS; MLA
PLN	075008275	HJ	1485		BANGKOK	THA	100E31 13N48	9	20	1	0.0		A	50	30			
PLN	075008275	HN	1485		BANGKOK	THA	100E31 13N48	9	20	1	0.0		A	50	30			
MOD	121115760	HJ	1404		SUPHAN BURI-1	THA	100E02 14N27	9	18	8	10.7		A	96	30			
MOD	121115760	HN	1404		SUPHAN BURI-1	THA	100E02 14N27	9	18	8	10.7		A	96	30			IND

Partie / Part / Parte A

AMS	Id No	JN	Freq	Sync	Site name	Ctry	Geocoords	Pr	Bdw	Power	Emrp	Azm	Ant	Hgt	Cond	Rmks	Coord_A	Coord_B
PLN	075005148	HJ	1161		NAKHON PHANOM	THA	104E42 17N15	9	20	10	10.4		A	64	10			
PLN	075005148	HN	1161		NAKHON PHANOM	THA	104E42 17N15	9	20	10	10.4		A	64	10			
MOD	121115742	HJ	1440		NAKHON PHANOM-2	THA	104E34 17N20	9	18	10	10.7		A	64	3			
MOD	121115742	HN	1440		NAKHON PHANOM-2	THA	104E34 17N20	9	18	10	10.7		A	64	3		CHN; MLA	
PLN	075007319	HJ	1440		BANGKOK	THA	100E33 13N43	9	20	10	10.4		A	52	30			
PLN	075007319	HN	1440		BANGKOK	THA	100E33 13N43	9	20	10	10.4		A	52	30			
MOD	121115756	HJ	1440		SAMUT SAKHON-2	THA	100E17 13N39	9	18	10	10.4		A	54	30			
MOD	121115756	HN	1440		SAMUT SAKHON-2	THA	100E17 13N39	9	18	10	10.4		A	54	30			
PLN	088000177	HJ	1449		CHUMPHON	THA	099E10 10N30	9	20	5	7.0		A	51	10			
PLN	088000177	HN	1449		CHUMPHON	THA	099E10 10N30	9	20	5	7.0		A	51	10			
MOD	121115772	HJ	1449		CHUMPHON-3	THA	099E06 10N30	9	18	8	9.4		A	51	30			
MOD	121115772	HN	1449		CHUMPHON-3	THA	099E06 10N30	9	18	8	9.4		A	51	30			
PLN	075008280	HJ	1485		PHITSANULOK	THA	100E22 16N49	9	20	1	0.0		A	50	30			
PLN	075008280	HN	1485		PHITSANULOK	THA	100E22 16N49	9	20	1	0.0		A	50	30			
MOD	121115764	HJ	1449		PHICHIT-1	THA	100E08 16N29	9	18	8	9.5		A	54	30			
MOD	121115764	HN	1449		PHICHIT-1	THA	100E08 16N29	9	18	8	9.5		A	54	30			
ADD	121131684	HJ	1467		LENTINI	I	015E01 37N21	0	9	0.5	-3.0		A	40	1			
ADD	121131684	HN	1467		LENTINI	I	015E01 37N21	0	9	0.5	-3.0		A	40	1			
PLN	075007522	HJ	1467		BANGKOK	THA	100E43 14N04	9	20	100	23.0	270	B		30			
PLN	075007522	HN	1467		BANGKOK	THA	100E43 14N04	9	20	100	23.0	270	B		30			
MOD	121115701	HJ	1467		PATHUM THANI-7	THA	100E42 14N04	9	18	100	22.3		A	113	10			
MOD	121115701	HN	1467		PATHUM THANI-7	THA	100E42 14N04	9	18	100	22.3		A	113	10		CHN; INS	
ADD	121131680	HJ	1503		TRIESTE MUGGIA	I	013E44 45N36	0	9	0.5	-3.0		A	40	1		MNE	
ADD	121131680	HN	1503		TRIESTE MUGGIA	I	013E44 45N36	0	9	0.5	-3.0		A	40	1			
PLN	075008686	HJ	1512		CHIANG RAI	THA	099E55 19N05	9	20	10	10.4		A	50	1			
PLN	075008686	HN	1512		CHIANG RAI	THA	099E55 19N05	9	20	10	10.4		A	50	1			
MOD	121115766	HJ	1512		PHAYAO-1	THA	099E52 19N11	9	18	10	10.5		A	54	3			
MOD	121115766	HN	1512		PHAYAO-1	THA	099E52 19N11	9	18	10	10.5		A	54	3			
ADD	121131681	HJ	1521		TARVISIO	I	013E35 46N30	0	9	0.5	-3.0		A	30	1			
ADD	121131681	HN	1521		TARVISIO	I	013E35 46N30	0	9	0.5	-3.0		A	30	1			
PLN	075005149	HJ	1161		RAYONG	THA	101E14 12N40	9	20	10	10.4		A	65	10			
PLN	075005149	HN	1161		RAYONG	THA	101E14 12N40	9	20	10	10.4		A	65	10			
MOD	121115743	HJ	1530		CHANTHABURI-5	THA	102E03 12N34	9	18	10	10.8		A	65	3			
MOD	121115743	HN	1530		CHANTHABURI-5	THA	102E03 12N34	9	18	10	10.8		A	65	3		INS; MLA	
ADD	121131682	HJ	1539		MURIS-RAGOGNA	I	012E59 46N11	0	9	0.5	-3.0		A	30	1			
ADD	121131682	HN	1539		MURIS-RAGOGNA	I	012E59 46N11	0	9	0.5	-3.0		A	30	1		D	

Partie / Part / Parte A

<i>AMS</i>	<i>Id No</i>	<i>JN</i>	<i>Freq</i>	<i>Sync</i>	<i>Site name</i>	<i>Ctry</i>	<i>Geocoords</i>	<i>Pr</i>	<i>Bdw</i>	<i>Power</i>	<i>Emrp</i>	<i>Azm</i>	<i>Ant</i>	<i>Hgt</i>	<i>Cond</i>	<i>Rmks</i>	<i>Coord_A</i>	<i>Coord_B</i>
PLN	075007320	HJ	1440		SAMUT SAKHON	THA	100E18 13N40	9	20	10	10.4		A	52	30			
PLN	075007320	HN	1440		SAMUT SAKHON	THA	100E18 13N40	9	20	10	10.4		A	52	30			
MOD	121115757	HJ	1539		KANCHANABURI-3	THA	099E28 14N04	9	18	10	12.0		A	97	30			
MOD	121115757	HN	1539		KANCHANABURI-3	THA	099E28 14N04	9	18	10	12.0		A	97	30		CBG	
PLN	075009018	HJ	1557		PHETCHABUN	THA	101E14 16N48	9	20	10	10.4		A	48	1			
PLN	075009018	HN	1557		PHETCHABUN	THA	101E14 16N48	9	20	10	10.4		A	48	1			
MOD	121115768	HJ	1557		PHETCHABUN-4	THA	101E12 16N45	9	18	10	10.4		A	48	10			
MOD	121115768	HN	1557		PHETCHABUN-4	THA	101E12 16N45	9	18	10	10.4		A	48	10			
ADD	121131678	HJ	1593		SALERNO SERRE	I	015E10 40N34	0	9	0.1	-10.0		A	30	1			
ADD	121131678	HN	1593		SALERNO SERRE	I	015E10 40N34	0	9	0.1	-10.0		A	30	1			

Partie / Part / Parte B

<i>AMS</i>	<i>Id No</i>	<i>JN</i>	<i>Freq</i>	<i>Sync</i>	<i>Site name</i>	<i>Ctry</i>	<i>Geocoords</i>	<i>Pr</i>	<i>Bdw</i>	<i>Power</i>	<i>Emrp</i>	<i>Azm</i>	<i>Ant</i>	<i>Hgt</i>	<i>Cond</i>	<i>Rmks</i>	<i>Coord_A</i>	<i>Coord_B</i>
PLN	075004564	HJ	1080	S	NAKHON SAWAN	THA	100E08 15N40	9	20	10	10.4		A	69	30			
PLN	075004564	HN	1080	S	NAKHON SAWAN	THA	100E08 15N40	9	20	10	10.4		A	69	30			
MOD	121115738	HJ	1080		NAKHON SAWAN-3	THA	100E07 15N40	9	18	10	10.4		A	72	30			
MOD	121115738	HN	1080		NAKHON SAWAN-3	THA	100E07 15N40	9	18	10	10.4		A	72	30			
ADD	121069428	HJ	1170		Tizi Ouzou	ALG	004E13 36N37	0	9	251.2	24.0		A	64	1	A/194		
ADD	121069428	HN	1170		Tizi Ouzou	ALG	004E13 36N37	0	9	9.6	9.8		A	64	1	A/194		
PLN	075006887	HJ	1377		PHITSANULOK	THA	100E16 16N50	9	20	10	10.4		A	54	30			
PLN	075006887	HN	1377		PHITSANULOK	THA	100E16 16N50	9	20	10	10.4		A	54	30			
MOD	121115754	HJ	1377		PHITSANULOK-6	THA	100E15 16N50	9	18	10	10.4		A	54	30			
MOD	121115754	HN	1377		PHITSANULOK-6	THA	100E15 16N50	9	18	10	10.4		A	54	30			
PLN	075007193	HJ	1422		PHITSANULOK	THA	100E15 16N48	9	20	10	10.4		A	45	30			
PLN	075007193	HN	1422		PHITSANULOK	THA	100E15 16N48	9	20	10	10.4		A	45	30			
MOD	121115711	HJ	1422		PHITSANULOK-7	THA	100E15 16N48	9	18	10	10.4		A	50	30			
MOD	121115711	HN	1422		PHITSANULOK-7	THA	100E15 16N48	9	18	10	10.4		A	50	30			

Annex to notifying administration

I

Modification to the Plan					Affected assignment in the Plan				Worst affected point	
Freq	Ctry	Site name	Id No	HJ/HN	Ctry	Freq	Site name	Id No	Azm	Eu_Inc
1377	I	GORIZIA	121131679	HJ	HRV	1377	KUMROVEC	075006898	280	1.51
1503	I	TRIESTE MUGGIA	121131680	HJ	MNE	1503	ULCINJ	075008642	300	0.54
1539	I	MURIS-RAGOGNA	121131682	HN	D	1539	MAINFLINGEN	075008838	140	0.84

Annex to notifying administration

THA

Modification to the Plan					Affected assignment in the Plan				Worst affected point	
Freq	Ctry	Site name	Id No	HJ/HN	Ctry	Freq	Site name	Id No	Azm	Eu_Inc
585	THA	PHRAE-1	121115719	HN	CHN	585 LANZHOU		075000641	140	0.51
	THA	PHRAE-1	121115719	HN	VTN	585 NHATRANG		075000678	280	2.04
594	THA	BANGKOK-3	121115715	HN	MLA	594 KAJANG		075000710	320	3.44
	THA	BANGKOK-3	121115715	HJ	VTN	594 VOV Da Nang 594 kHz		114137900	240	1.02
612	THA	CHIANG MAI-1	121115695	HN	CHN	612 BARKAM		075000829	200	0.72
	THA	CHIANG MAI-1	121115695	HN	IND	612 AIJAL		075000836	100	2.14
	THA	CHIANG MAI-1	121115695	HN	MLA	612 KANGAR		075000845	260	0.60
	THA	CHIANG MAI-1	121115695	HN	VTN	612 SAIGON		075000867	0	0.70
621	THA	KHON KAEN-2	121115699	HN	IND	621 PATNA		075000893	120	1.26
	THA	KHON KAEN-2	121115699	HN	MLA	621 SEGAMAT		075000903	260	3.41
639	THA	LAMPHUN-1	121115702	HN	CHN	639 DONGCHUAN		075001060	220	0.56
	THA	LAMPHUN-1	121115702	HN	CHN	639 LIJIANG		075001071	140	0.50
	THA	LAMPHUN-1	121115702	HN	CHN	639 LINCANG		075001072	180	1.07
	THA	LAMPHUN-1	121115702	HN	CHN	639 LUCHUN		075001074	240	0.72
	THA	LAMPHUN-1	121115702	HN	CHN	639 LUCHUN XIAN		075001082	240	0.73
	THA	LAMPHUN-1	121115702	HN	CHN	639 LUXI		075001076	100	0.88
	THA	LAMPHUN-1	121115702	HN	CHN	639 XIAGUAN		075001094	180	0.77
666	THA	SURIN-1	121115752	HN	MLA	666 PENANG		075001308	0	1.61
	THA	TAK-1	121115720	HN	MLA	666 PENANG		075001308	280	0.86
684	THA	N SITHAMMARAT-2	121115769	HN	CHN	684 HAIKOU		075001403	200	1.87
	THA	N SITHAMMARAT-2	121115769	HJ	IND	684 PT BLAIR		075001423	120	12.23
	THA	N SITHAMMARAT-2	121115769	HN	IND	684 PT BLAIR		075001423	80	4.86
	THA	N SITHAMMARAT-2	121115769	HN	INS	684 Depok-1		120234554	0	1.06
	THA	UDON THANI-1	121115767	HN	CHN	684 HAIKOU		075001403	280	2.75
	THA	UDON THANI-1	121115767	HN	IND	684 PT BLAIR		075001423	80	0.53
738	THA	SONGKHLA-2	121115725	HJ	CBG	738 PHNOM PENH		075001834	200	1.27
	THA	SONGKHLA-2	121115725	HJ	IND	738 PT BLAIR		075001865	140	2.88
	THA	SONGKHLA-2	121115725	HN	INS	738 Tangerang-1		120234558	280	0.68
747	THA	BANGKOK-7	121115724	HN	CHN	747 JINGDONG		075001904	200	2.02
	THA	BANGKOK-7	121115724	HN	CHN	747 KUNMING		075001905	200	1.32
	THA	BANGKOK-7	121115724	HN	CHN	747 TENGCHONG		075001906	140	1.40
	THA	BANGKOK-7	121115724	HN	CHN	747 ZHONGDIAN		075001907	140	0.61
	THA	BANGKOK-7	121115724	HN	INS	747 BENGKULU-1		075001919	20	0.57
	THA	UDON THANI-2	121115734	HN	CHN	747 JINGDONG		075001904	160	7.30

Annex to notifying administration

THA

Modification to the Plan					Affected assignment in the Plan				Worst affected point	
Freq	Ctry	Site name	Id No	HJ/HN	Ctry	Freq	Site name	Id No	Azm	Eu_Inc
	THA	UDON THANI-2	121115734	HN	CHN	747 KUNMING		075001905	180	6.72
	THA	UDON THANI-2	121115734	HN	CHN	747 TENGCHONG		075001906	120	4.62
	THA	UDON THANI-2	121115734	HN	CHN	747 ZHONGDIAN		075001907	140	2.86
	THA	UDON THANI-2	121115734	HN	INS	747 BENGKULU-1		075001919	20	0.65
774	THA	RAYONG-1	121115730	HN	MLA	774 SELAMA		075002207	0	7.60
783	THA	KAMPHAENG PHET-1	121115773	HN	CHN	783 COMA		075002238	160	0.55
	THA	KAMPHAENG PHET-1	121115773	HN	CHN	783 MEDO		075002241	180	0.52
	THA	KAMPHAENG PHET-1	121115773	HN	VTN	783 CANTHO		075002284	0	0.68
	THA	RANONG-1	121115704	HJ	VTN	783 CANTHO		075002284	260	2.50
792	THA	BANGKOK-8	121115693	HN	SNG	792 SINGAPORE 1		075002332	280	0.52
828	THA	N SITHAMMARAT-3	121115749	HJ	MLA	837 KOTA BAHRU		075002604	340	2.74
	THA	N SITHAMMARAT-3	121115749	HN	SNG	828 SINGAPORE 1		075002568	240	2.11
	THA	N SITHAMMARAT-3	121115749	HJ	VTN	828 Tien Giang 828 kHz		114137910	300	0.77
	THA	SUKHOTHAI-1	121115726	HJ	CHN	828 HAIKOU		075002525	260	2.05
	THA	SUKHOTHAI-1	121115726	HN	CHN	828 HAIKOU		075002525	300	2.50
	THA	SUKHOTHAI-1	121115726	HN	CHN	828 HUAIJI		075002526	240	0.63
	THA	SUKHOTHAI-1	121115726	HN	CHN	828 MAOMING		075002528	240	1.34
	THA	SUKHOTHAI-1	121115726	HN	IND	828 SILCHAR		075002548	160	4.73
	THA	SUKHOTHAI-1	121115726	HN	SNG	828 SINGAPORE 1		075002568	320	1.00
	THA	SUKHOTHAI-1	121115726	HJ	VTN	828 Son La 828 kHz		114137882	240	9.76
	THA	SUKHOTHAI-1	121115726	HN	VTN	828 Son La 828 kHz		114137882	240	2.44
	THA	SUKHOTHAI-1	121115726	HN	VTN	828 Tien Giang 828 kHz		114137910	280	0.50
855	THA	PRACHIN BURI-1	121115714	HN	CHN	855 BIJIANG		075002694	140	2.06
	THA	PRACHIN BURI-1	121115714	HN	CHN	855 BINCHUAN		075002695	160	2.56
	THA	PRACHIN BURI-1	121115714	HN	CHN	855 CHANGNING		075002697	140	3.11
	THA	PRACHIN BURI-1	121115714	HN	CHN	855 GEJIU		075002708	200	4.27
	THA	PRACHIN BURI-1	121115714	HN	CHN	855 JIANHE		075002716	200	0.59
	THA	PRACHIN BURI-1	121115714	HN	CHN	855 JINGHONG		075002719	160	5.76
	THA	PRACHIN BURI-1	121115714	HN	CHN	855 LINGSHAN		075002726	220	1.36
	THA	PRACHIN BURI-1	121115714	HN	CHN	855 LIUZHOU		075002728	220	1.04
	THA	PRACHIN BURI-1	121115714	HN	CHN	855 LONGLIN		075002730	200	2.32
	THA	PRACHIN BURI-1	121115714	HN	CHN	855 MEITAN		075002734	160	0.56
	THA	PRACHIN BURI-1	121115714	HN	CHN	855 NAYONG		075002739	200	1.11
	THA	PRACHIN BURI-1	121115714	HN	CHN	855 PINGGUO		075002741	240	1.96

Annex to notifying administration

THA

Modification to the Plan					Affected assignment in the Plan				Worst affected point	
Freq	Ctry	Site name	Id No	HJ/HN	Ctry	Freq	Site name	Id No	Azm	Eu_Inc
	THA	PRACHIN BURI-1	121115714	HN	CHN	855	PINGNAN	075002742	240	0.88
	THA	PRACHIN BURI-1	121115714	HN	CHN	855	QUJING	075002746	180	2.24
	THA	PRACHIN BURI-1	121115714	HN	CHN	855	ZHAOTONG	075002775	220	1.24
	THA	PRACHIN BURI-1	121115714	HN	CHN	855	ZHENFENG	075002776	280	1.82
	THA	PRACHIN BURI-1	121115714	HN	INS	855	MEDAN	075002809	340	4.99
909	THA	LOEI-1	121115703	HN	CHN	909	XICHANG	116182057	180	0.62
936	THA	PATTANI-1	121115731	HN	INS	936	Sukabumi-1	120234572	0	1.10
	THA	PATTANI-1	121115731	HJ	MLA	945	TRONOH	075003461	0	1.10
945	THA	KALASIN-1	121115712	HN	CHN	945	ANHUA	075003385	280	3.27
	THA	KALASIN-1	121115712	HN	CHN	945	CHANGSHA SHI	075003390	240	2.34
	THA	KALASIN-1	121115712	HN	CHN	945	CHUXIONG	075003392	120	7.24
	THA	KALASIN-1	121115712	HN	CHN	945	JINGDONG	075003403	120	7.13
	THA	KALASIN-1	121115712	HN	CHN	945	JINGSHAN	075003404	220	1.07
	THA	KALASIN-1	121115712	HN	CHN	945	KUNMING	075003406	140	8.17
	THA	KALASIN-1	121115712	HN	CHN	945	LANZHOU	075003407	140	0.83
	THA	KALASIN-1	121115712	HN	CHN	945	LEIYANG	075003408	260	3.01
	THA	KALASIN-1	121115712	HN	CHN	945	LINTAN	075003410	160	1.10
	THA	KALASIN-1	121115712	HN	CHN	945	NINGYUAN	075003414	240	3.34
	THA	KALASIN-1	121115712	HN	CHN	945	PUER	075003416	120	8.05
	THA	KALASIN-1	121115712	HN	CHN	945	QIANYANG	075003417	240	4.13
	THA	KALASIN-1	121115712	HN	CHN	945	TENGCHONG	075003423	100	4.44
	THA	KALASIN-1	121115712	HN	CHN	945	TIANSHUI SHI	075003424	160	1.20
	THA	KALASIN-1	121115712	HN	CHN	945	TONGLING	075003425	180	0.56
	THA	KALASIN-1	121115712	HN	CHN	945	WEIXI	075003427	120	3.67
	THA	KALASIN-1	121115712	HN	CHN	945	WENSHAN	075003428	160	9.73
	THA	KALASIN-1	121115712	HN	CHN	945	WUFENG	075003429	220	2.32
	THA	KALASIN-1	121115712	HN	CHN	945	XIANNING	075003430	240	1.07
	THA	KALASIN-1	121115712	HN	CHN	945	YONGSHUN	075003434	220	3.53
	THA	KALASIN-1	121115712	HN	CHN	945	YUNLONG	075003435	120	4.71
	THA	KALASIN-1	121115712	HN	CHN	945	ZHONGDIAN	075003436	120	3.50
	THA	KALASIN-1	121115712	HN	MLA	945	JOHORE BAHRU	075003460	40	3.23
	THA	KALASIN-1	121115712	HN	MLA	945	TRONOH	075003461	20	4.70
963	THA	BANGKOK-13	121115728	HN	BGD	963	SYLHET	075003546	120	1.06
	THA	BANGKOK-13	121115728	HN	MLA	963	KUALATRENGGANU	075003585	40	2.12

Annex to notifying administration

THA

Modification to the Plan					Affected assignment in the Plan				Worst affected point	
Freq	Ctry	Site name	Id No	HJ/HN	Ctry	Freq	Site name	Id No	Azm	Eu_Inc
999	THA	CHIANG RAI-2	121115771	HN	CHN	999	GUIYANG	075003866	240	0.95
1008	THA	NAKHON RATCHASIMA-3	121115733	HN	MLA	1008	MALACCA	075003949	20	0.94
1044	THA	N SITHAMMARAT-4	121115736	HN	INS	1044	SIBOLGA	075004283	20	8.28
	THA	N SITHAMMARAT-4	121115736	HN	MLA	1044	SIMANGGANG	075004286	240	0.55
1053	THA	BANGKOK-16	121115737	HN	CHN	1053	DONGCHUAN	075004320	140	1.10
	THA	BANGKOK-16	121115737	HN	CHN	1053	LIJIANG	075004321	120	0.76
	THA	BANGKOK-16	121115737	HN	CHN	1053	LINCANG	075004322	100	1.22
	THA	BANGKOK-16	121115737	HN	CHN	1053	LUCHUN	075004323	100	1.53
	THA	BANGKOK-16	121115737	HN	CHN	1053	LUXI	075004324	120	0.95
	THA	BANGKOK-16	121115737	HN	CHN	1053	WENSHAN XIAN	075004325	200	1.56
	THA	BANGKOK-16	121115737	HN	CHN	1053	XIAGUAN	075004326	120	1.03
	THA	BANGKOK-16	121115737	HN	MLA	1053	MERSING	075004353	80	0.71
	THA	LAMPANG-2	121115770	HN	BGD	1053	RANGPUR	075004317	140	1.21
	THA	LAMPANG-2	121115770	HN	CHN	1053	DONGCHUAN	075004320	200	7.79
	THA	LAMPANG-2	121115770	HN	CHN	1053	LIJIANG	075004321	140	7.29
	THA	LAMPANG-2	121115770	HN	CHN	1053	LINCANG	075004322	200	9.98
	THA	LAMPANG-2	121115770	HN	CHN	1053	LUCHUN	075004323	280	9.35
	THA	LAMPANG-2	121115770	HN	CHN	1053	LUXI	075004324	140	9.08
	THA	LAMPANG-2	121115770	HN	CHN	1053	WENSHAN XIAN	075004325	280	8.31
	THA	LAMPANG-2	121115770	HN	CHN	1053	XIAGUAN	075004326	180	8.84
	THA	LAMPANG-2	121115770	HN	IND	1053	TUTICORIN	075004345	140	0.56
	THA	LAMPANG-2	121115770	HN	MLA	1053	MERSING	075004353	80	0.93
1080	THA	YALA-3	121115739	HJ	MLA	1089	GRIK	075004618	0	9.10
1098	THA	SONGKHLA-3	121115709	HJ	MLA	1089	GRIK	075004618	340	2.64
1107	THA	KHON KAEN-5	121115729	HN	MLA	1107	TEMERLOH	075004752	60	0.88
	THA	SAMUT SAKHON-1	121115696	HN	MLA	1107	TEMERLOH	075004752	0	3.13
1116	THA	PHITSANULOK-3	121115759	HN	CHN	1116	DUKOU	075004779	240	0.73
1179	THA	BANGKOK-20	121115710	HN	INS	1179	PADANG-1	075005236	340	2.65
1188	THA	PHITSANULOK-5	121115758	HN	CHN	1188	KUNMING	075005265	260	1.04
	THA	PHITSANULOK-5	121115758	HN	MLA	1188	KANGAR	075005292	0	0.83
	THA	SA KAE0-1	121115718	HN	AUS	1188	EXMOUTH WA	075005261	180	0.88
	THA	SA KAE0-1	121115718	HN	CHN	1188	KUNMING	075005265	220	2.69
	THA	SA KAE0-1	121115718	HN	MLA	1188	KANGAR	075005292	20	6.17
1197	THA	LOP BURI-4	121115722	HN	CHN	1197	CHUXIONG	075005319	140	1.48

Annex to notifying administration

THA

Modification to the Plan					Affected assignment in the Plan				Worst affected point	
Freq	Ctry	Site name	Id No	HJ/HN	Ctry	Freq	Site name	Id No	Azm	Eu_Inc
	THA	LOP BURI-4	121115722	HN	CHN	1197 PUER		075005320	60	1.40
	THA	LOP BURI-4	121115722	HN	CHN	1197 WENSHAN		075005322	20	1.70
	THA	LOP BURI-4	121115722	HN	CHN	1197 YUNLONG		075005323	80	0.60
1215	THA	UBON RATCHATHANI-4	121115755	HN	CHN	1215 DINGNAN		075005455	260	0.60
	THA	UBON RATCHATHANI-4	121115755	HN	CHN	1215 HUIZHOU		075005464	240	0.80
	THA	UBON RATCHATHANI-4	121115755	HN	CHN	1215 YINGDE		075005504	240	0.97
	THA	UBON RATCHATHANI-4	121115755	HN	CHN	1215 ZHANJIANG		075005508	220	3.45
1242	THA	PHETCHABUN-3	121115745	HN	CBG	1242 PHNOM PENH		075005710	180	1.20
	THA	PHETCHABUN-3	121115745	HN	CHN	1242 BIJIANG		075005713	120	2.32
	THA	PHETCHABUN-3	121115745	HN	CHN	1242 BINCHUAN		075005714	140	3.06
	THA	PHETCHABUN-3	121115745	HN	CHN	1242 CHANGNING		075005715	180	3.46
	THA	PHETCHABUN-3	121115745	HN	CHN	1242 GEJIU		075005716	260	3.36
	THA	PHETCHABUN-3	121115745	HN	CHN	1242 JINGHONG		075005717	220	4.79
	THA	PHETCHABUN-3	121115745	HN	CHN	1242 QIJING		075005718	240	2.85
	THA	PHETCHABUN-3	121115745	HN	CHN	1242 ZHAOTONG		075005719	180	2.14
1269	THA	BANGKOK-23	121115747	HN	IND	1269 AGARTALA		075005903	140	2.64
	THA	BANGKOK-23	121115747	HN	INS	1269 PONTIANAK		075005909	280	0.92
	THA	SONGKHLA-4	121115697	HN	IND	1269 AGARTALA		075005903	300	0.62
	THA	SONGKHLA-4	121115697	HN	INS	1269 PONTIANAK		075005909	240	0.56
	THA	SONGKHLA-4	121115697	HJ	MLA	1260 KUALA DUNGUN		075005865	40	0.53
1287	THA	UTTARADIT-1	121115732	HN	BGD	1287 BARISAL		075006007	100	1.52
	THA	UTTARADIT-1	121115732	HN	CHN	1287 HAIYUAN		075006010	240	0.65
	THA	UTTARADIT-1	121115732	HN	INS	1287 PALEMBANG		075006021	0	0.57
1305	THA	SARABURI-3	121115750	HN	CHN	1305 BEIHAI		075006107	280	0.84
	THA	SARABURI-3	121115750	HN	CHN	1305 BOSE		075006109	280	0.88
	THA	SARABURI-3	121115750	HN	CHN	1305 DONGCHUAN		075006118	180	1.48
	THA	SARABURI-3	121115750	HN	CHN	1305 DUKOU		075006119	180	1.32
	THA	SARABURI-3	121115750	HN	CHN	1305 GUIYANG		075006125	200	0.50
	THA	SARABURI-3	121115750	HN	CHN	1305 HECHI		075006128	200	0.70
	THA	SARABURI-3	121115750	HN	CHN	1305 HEKOU		075006129	220	1.95
	THA	SARABURI-3	121115750	HN	CHN	1305 LIJIANG		075006138	140	1.13
	THA	SARABURI-3	121115750	HN	CHN	1305 LINCANG		075006139	40	1.82
	THA	SARABURI-3	121115750	HN	CHN	1305 LUCHUN		075006142	140	2.06
	THA	SARABURI-3	121115750	HN	CHN	1305 LUXI		075006143	100	1.11

Annex to notifying administration

THA

Modification to the Plan					Affected assignment in the Plan				Worst affected point	
Freq	Ctry	Site name	Id No	HJ/HN	Ctry	Freq	Site name	Id No	Azm	Eu_Inc
	THA	SARABURI-3	121115750	HN	CHN	1305	NANNING	075006146	140	0.79
	THA	SARABURI-3	121115750	HN	CHN	1305	PINGLE	075006149	180	0.56
	THA	SARABURI-3	121115750	HN	CHN	1305	QIUBEI	075006153	200	1.67
	THA	SARABURI-3	121115750	HN	CHN	1305	WEINING	075006168	220	1.13
	THA	SARABURI-3	121115750	HN	CHN	1305	XIAGUAN	075006171	100	1.50
	THA	SARABURI-3	121115750	HN	CHN	1305	XINGYI	075006175	180	1.47
	THA	SARABURI-3	121115750	HN	CHN	1305	YOUYANG	075006184	40	0.50
	THA	SARABURI-3	121115750	HN	CHN	1305	YULIN 2	075006185	140	0.73
1314	THA	KHON KAEN-7	121115698	HN	MLA	1314	MERSING	075006293	0	0.88
1359	THA	SAKON NAKHON-3	121115762	HN	CHN	1359	ANSHUN SHI	075006615	180	3.85
	THA	SAKON NAKHON-3	121115762	HN	CHN	1359	BIJIE	075006619	180	3.34
	THA	SAKON NAKHON-3	121115762	HN	CHN	1359	BINCHUAN	075006620	100	3.04
	THA	SAKON NAKHON-3	121115762	HN	CHN	1359	CHANGNING	075006623	60	2.80
	THA	SAKON NAKHON-3	121115762	HN	CHN	1359	CHANGTING	075006624	240	0.92
	THA	SAKON NAKHON-3	121115762	HN	CHN	1359	CHENGKOU	075006625	240	0.57
	THA	SAKON NAKHON-3	121115762	HN	CHN	1359	DEJIANG	075006627	220	2.14
	THA	SAKON NAKHON-3	121115762	HN	CHN	1359	FENGJIE	075006628	260	0.75
	THA	SAKON NAKHON-3	121115762	HN	CHN	1359	GARZE	075006630	180	1.13
	THA	SAKON NAKHON-3	121115762	HN	CHN	1359	GEJIU	075006631	120	5.47
	THA	SAKON NAKHON-3	121115762	HN	CHN	1359	GUI XIAN	075006633	240	4.29
	THA	SAKON NAKHON-3	121115762	HN	CHN	1359	JINGHONG	075006644	60	3.08
	THA	SAKON NAKHON-3	121115762	HN	CHN	1359	KANGDING	075006646	180	2.05
	THA	SAKON NAKHON-3	121115762	HN	CHN	1359	LESHAN	075006650	200	2.31
	THA	SAKON NAKHON-3	121115762	HN	CHN	1359	LUODIAN	075006652	180	4.28
	THA	SAKON NAKHON-3	121115762	HN	CHN	1359	LUSHUI XIAN	075006618	60	2.49
	THA	SAKON NAKHON-3	121115762	HN	CHN	1359	LUZHOU	075006654	200	2.49
	THA	SAKON NAKHON-3	121115762	HN	CHN	1359	MAQEN	075006655	160	0.50
	THA	SAKON NAKHON-3	121115762	HN	CHN	1359	MIAN XIAN	075006657	180	0.54
	THA	SAKON NAKHON-3	121115762	HN	CHN	1359	NANCHONG SHI	075006658	200	1.34
	THA	SAKON NAKHON-3	121115762	HN	CHN	1359	PINGXIANG 2	075006663	320	6.82
	THA	SAKON NAKHON-3	121115762	HN	CHN	1359	QINGLONG	075006665	200	4.48
	THA	SAKON NAKHON-3	121115762	HN	CHN	1359	QINZHOU	075006666	220	5.64
	THA	SAKON NAKHON-3	121115762	HN	CHN	1359	QUJING	075006668	160	4.82
	THA	SAKON NAKHON-3	121115762	HN	CHN	1359	RONGJIANG	075006669	220	3.37

Annex to notifying administration

THA

Modification to the Plan					Affected assignment in the Plan				Worst affected point	
Freq	Ctry	Site name	Id No	HJ/HN	Ctry	Freq	Site name	Id No	Azm	Eu_Inc
	THA	SAKON NAKHON-3	121115762	HN	CHN	1359	SERXU	075006670	160	0.71
	THA	SAKON NAKHON-3	121115762	HN	CHN	1359	SHIBING	075006673	220	2.53
	THA	SAKON NAKHON-3	121115762	HN	CHN	1359	WAYUAN XIAN	110014935	60	2.72
	THA	SAKON NAKHON-3	121115762	HN	CHN	1359	XIANGCHENG	075006682	120	2.11
	THA	SAKON NAKHON-3	121115762	HN	CHN	1359	YINGJIANG XIAN	110014928	80	2.30
	THA	SAKON NAKHON-3	121115762	HN	CHN	1359	ZHAOJUE	075006686	160	3.03
	THA	SAKON NAKHON-3	121115762	HN	CHN	1359	ZHAOTONG	075006687	160	3.30
	THA	SAKON NAKHON-3	121115762	HN	CHN	1359	ZHENKANG XIAN	110014936	0	2.52
	THA	SAKON NAKHON-3	121115762	HN	CHN	1359	ZIGONG	075006691	200	2.20
	THA	SAKON NAKHON-3	121115762	HN	CHN	1359	ZUNYI SHI	075006693	180	2.69
1404	THA	SONGKHLA-5	121115700	HN	AUS	1404	Busselton	107013047	220	1.49
	THA	SONGKHLA-5	121115700	HN	AUS	1404	COCOS ISLANDS	075007020	280	1.79
	THA	SONGKHLA-5	121115700	HN	IND	1404	TEZPUR	075007040	200	0.85
	THA	SONGKHLA-5	121115700	HN	INS	1404	DJAKARTA	075007042	0	2.55
	THA	SONGKHLA-5	121115700	HN	MLA	1395	KUANTAN	075006988	260	1.06
	THA	SUPHAN BURI-1	121115760	HN	IND	1404	TEZPUR	075007040	180	0.78
1440	THA	NAKHON PHANOM-2	121115742	HN	CHN	1440	HE XIAN	075007274	220	1.65
	THA	NAKHON PHANOM-2	121115742	HN	CHN	1440	LINGSHAN	075007275	240	4.00
	THA	NAKHON PHANOM-2	121115742	HN	CHN	1440	LIUZHOU	075007276	200	3.06
	THA	NAKHON PHANOM-2	121115742	HN	CHN	1440	LONGLIN	075007277	180	3.98
	THA	NAKHON PHANOM-2	121115742	HN	CHN	1440	PINGGUO	075007278	200	4.65
	THA	NAKHON PHANOM-2	121115742	HN	CHN	1440	PINGNAN	075007279	220	2.78
	THA	NAKHON PHANOM-2	121115742	HN	CHN	1440	QUANZHOU 2	075007280	220	1.24
	THA	NAKHON PHANOM-2	121115742	HN	MLA	1440	TEMERLOH	075007305	80	0.52
1467	THA	PATHUM THANI-7	121115701	HN	CHN	1467	CHENGDU	075007484	220	1.80
	THA	PATHUM THANI-7	121115701	HN	INS	1467	Tanjungpinang-2	075007500	340	10.06
1530	THA	CHANTHABURI-5	121115743	HN	INS	1530	PADANG	075008788	320	3.39
	THA	CHANTHABURI-5	121115743	HN	MLA	1530	BINTULU	075008799	260	1.80
1539	THA	KANCHANABURI-3	121115757	HN	CBG	1539	PHNOM PENH	075008831	220	0.69

Annex to affected administration

AUS

Modification to the Plan					Affected assignment in the Plan				Worst affected point	
Freq	Ctry	Site name	Id No	HJ/HN	Ctry	Freq	Site name	Id No	Azm	Eu_Inc
1188	THA	SA KAE0-1	121115718	HN	AUS	1188	EXMOUTH WA	075005261	180	0.88
1404	THA	SONGKHLA-5	121115700	HN	AUS	1404	Busselton	107013047	220	1.49
	THA	SONGKHLA-5	121115700	HN	AUS	1404	COCOS ISLANDS	075007020	280	1.79

Annex to affected administration

BGD

Modification to the Plan					Affected assignment in the Plan				Worst affected point	
Freq	Ctry	Site name	Id No	HJ/HN	Ctry	Freq	Site name	Id No	Azm	Eu_Inc
963	THA	BANGKOK-13	121115728	HN	BGD	963	SYLHET	075003546	120	1.06
1053	THA	LAMPANG-2	121115770	HN	BGD	1053	RANGPUR	075004317	140	1.21
1287	THA	UTTARADIT-1	121115732	HN	BGD	1287	BARISAL	075006007	100	1.52

Annex to affected administration

CBG

Modification to the Plan					Affected assignment in the Plan				Worst affected point	
Freq	Ctry	Site name	Id No	HJ/HN	Ctry	Freq	Site name	Id No	Azm	Eu_Inc
738	THA	SONGKHLA-2	121115725	HJ	CBG	738	PHNOM PENH	075001834	200	1.27
1242	THA	PHETCHABUN-3	121115745	HN	CBG	1242	PHNOM PENH	075005710	180	1.20
1539	THA	KANCHANABURI-3	121115757	HN	CBG	1539	PHNOM PENH	075008831	220	0.69

Annex to affected administration

CHN

Modification to the Plan					Affected assignment in the Plan				Worst affected point	
Freq	Ctry	Site name	Id No	HJ/HN	Ctry	Freq	Site name	Id No	Azm	Eu_Inc
585	THA	PHRAE-1	121115719	HN	CHN	585	LANZHOU	075000641	140	0.51
612	THA	CHIANG MAI-1	121115695	HN	CHN	612	BARKAM	075000829	200	0.72
639	THA	LAMPHUN-1	121115702	HN	CHN	639	DONGCHUAN	075001060	220	0.56
	THA	LAMPHUN-1	121115702	HN	CHN	639	LIJIANG	075001071	140	0.50
	THA	LAMPHUN-1	121115702	HN	CHN	639	LINCANG	075001072	180	1.07
	THA	LAMPHUN-1	121115702	HN	CHN	639	LUCHUN	075001074	240	0.72
	THA	LAMPHUN-1	121115702	HN	CHN	639	LUCHUN XIAN	075001082	240	0.73
	THA	LAMPHUN-1	121115702	HN	CHN	639	LUXI	075001076	100	0.88
	THA	LAMPHUN-1	121115702	HN	CHN	639	XIAGUAN	075001094	180	0.77
684	THA	N SITHAMMARAT-2	121115769	HN	CHN	684	HAIKOU	075001403	200	1.87
	THA	UDON THANI-1	121115767	HN	CHN	684	HAIKOU	075001403	280	2.75
747	THA	BANGKOK-7	121115724	HN	CHN	747	JINGDONG	075001904	200	2.02
	THA	BANGKOK-7	121115724	HN	CHN	747	KUNMING	075001905	200	1.32
	THA	BANGKOK-7	121115724	HN	CHN	747	TENGCHONG	075001906	140	1.40
	THA	BANGKOK-7	121115724	HN	CHN	747	ZHONGDIAN	075001907	140	0.61
	THA	UDON THANI-2	121115734	HN	CHN	747	JINGDONG	075001904	160	7.30
	THA	UDON THANI-2	121115734	HN	CHN	747	KUNMING	075001905	180	6.72
	THA	UDON THANI-2	121115734	HN	CHN	747	TENGCHONG	075001906	120	4.62
	THA	UDON THANI-2	121115734	HN	CHN	747	ZHONGDIAN	075001907	140	2.86
783	THA	KAMPHAENG PHET-1	121115773	HN	CHN	783	COMA	075002238	160	0.55
	THA	KAMPHAENG PHET-1	121115773	HN	CHN	783	MEDO	075002241	180	0.52
828	THA	SUKHOTHAI-1	121115726	HJ	CHN	828	HAIKOU	075002525	260	2.05
	THA	SUKHOTHAI-1	121115726	HN	CHN	828	HAIKOU	075002525	300	2.50
	THA	SUKHOTHAI-1	121115726	HN	CHN	828	HUAIJI	075002526	240	0.63
	THA	SUKHOTHAI-1	121115726	HN	CHN	828	MAOMING	075002528	240	1.34
855	THA	PRACHIN BURI-1	121115714	HN	CHN	855	BIJIANG	075002694	140	2.06
	THA	PRACHIN BURI-1	121115714	HN	CHN	855	BINCHUAN	075002695	160	2.56
	THA	PRACHIN BURI-1	121115714	HN	CHN	855	CHANGNING	075002697	140	3.11
	THA	PRACHIN BURI-1	121115714	HN	CHN	855	GEJIU	075002708	200	4.27
	THA	PRACHIN BURI-1	121115714	HN	CHN	855	JIANHE	075002716	200	0.59
	THA	PRACHIN BURI-1	121115714	HN	CHN	855	JINGHONG	075002719	160	5.76
	THA	PRACHIN BURI-1	121115714	HN	CHN	855	LINGSHAN	075002726	220	1.36
	THA	PRACHIN BURI-1	121115714	HN	CHN	855	LIUZHOU	075002728	220	1.04
	THA	PRACHIN BURI-1	121115714	HN	CHN	855	LONGLIN	075002730	200	2.32

Annex to affected administration

CHN

<i>Modification to the Plan</i>					<i>Affected assignment in the Plan</i>				<i>Worst affected point</i>	
<i>Freq</i>	<i>Ctry</i>	<i>Site name</i>	<i>Id No</i>	<i>HJ/HN</i>	<i>Ctry</i>	<i>Freq</i>	<i>Site name</i>	<i>Id No</i>	<i>Azm</i>	<i>Eu_Inc</i>
	THA	PRACHIN BURI-1	121115714	HN	CHN	855	MEITAN	075002734	160	0.56
	THA	PRACHIN BURI-1	121115714	HN	CHN	855	NAYONG	075002739	200	1.11
	THA	PRACHIN BURI-1	121115714	HN	CHN	855	PINGGUO	075002741	240	1.96
	THA	PRACHIN BURI-1	121115714	HN	CHN	855	PINGNAN	075002742	240	0.88
	THA	PRACHIN BURI-1	121115714	HN	CHN	855	QUJING	075002746	180	2.24
	THA	PRACHIN BURI-1	121115714	HN	CHN	855	ZHAOTONG	075002775	220	1.24
	THA	PRACHIN BURI-1	121115714	HN	CHN	855	ZHENFENG	075002776	280	1.82
909	THA	LOEI-1	121115703	HN	CHN	909	XICHANG	116182057	180	0.62
945	THA	KALASIN-1	121115712	HN	CHN	945	ANHUA	075003385	280	3.27
	THA	KALASIN-1	121115712	HN	CHN	945	CHANGSHA SHI	075003390	240	2.34
	THA	KALASIN-1	121115712	HN	CHN	945	CHUXIONG	075003392	120	7.24
	THA	KALASIN-1	121115712	HN	CHN	945	JINGDONG	075003403	120	7.13
	THA	KALASIN-1	121115712	HN	CHN	945	JINGSHAN	075003404	220	1.07
	THA	KALASIN-1	121115712	HN	CHN	945	KUNMING	075003406	140	8.17
	THA	KALASIN-1	121115712	HN	CHN	945	LANZHOU	075003407	140	0.83
	THA	KALASIN-1	121115712	HN	CHN	945	LEIYANG	075003408	260	3.01
	THA	KALASIN-1	121115712	HN	CHN	945	LINTAN	075003410	160	1.10
	THA	KALASIN-1	121115712	HN	CHN	945	NINGYUAN	075003414	240	3.34
	THA	KALASIN-1	121115712	HN	CHN	945	PUER	075003416	120	8.05
	THA	KALASIN-1	121115712	HN	CHN	945	QIANYANG	075003417	240	4.13
	THA	KALASIN-1	121115712	HN	CHN	945	TENGCHONG	075003423	100	4.44
	THA	KALASIN-1	121115712	HN	CHN	945	TIANSHUI SHI	075003424	160	1.20
	THA	KALASIN-1	121115712	HN	CHN	945	TONGLING	075003425	180	0.56
	THA	KALASIN-1	121115712	HN	CHN	945	WEIXI	075003427	120	3.67
	THA	KALASIN-1	121115712	HN	CHN	945	WENSHAN	075003428	160	9.73
	THA	KALASIN-1	121115712	HN	CHN	945	WUFENG	075003429	220	2.32
	THA	KALASIN-1	121115712	HN	CHN	945	XIANNING	075003430	240	1.07
	THA	KALASIN-1	121115712	HN	CHN	945	YONGSHUN	075003434	220	3.53
	THA	KALASIN-1	121115712	HN	CHN	945	YUNLONG	075003435	120	4.71
	THA	KALASIN-1	121115712	HN	CHN	945	ZHONGDIAN	075003436	120	3.50
999	THA	CHIANG RAI-2	121115771	HN	CHN	999	GUIYANG	075003866	240	0.95
1053	THA	BANGKOK-16	121115737	HN	CHN	1053	DONGCHUAN	075004320	140	1.10
	THA	BANGKOK-16	121115737	HN	CHN	1053	LIJIANG	075004321	120	0.76
	THA	BANGKOK-16	121115737	HN	CHN	1053	LINCANG	075004322	100	1.22

Annex to affected administration

CHN

Modification to the Plan					Affected assignment in the Plan				Worst affected point	
Freq	Ctry	Site name	Id No	HJ/HN	Ctry	Freq	Site name	Id No	Azm	Eu_Inc
	THA	BANGKOK-16	121115737	HN	CHN	1053	LUCHUN	075004323	100	1.53
	THA	BANGKOK-16	121115737	HN	CHN	1053	LUXI	075004324	120	0.95
	THA	BANGKOK-16	121115737	HN	CHN	1053	WENSHAN XIAN	075004325	200	1.56
	THA	BANGKOK-16	121115737	HN	CHN	1053	XIAGUAN	075004326	120	1.03
	THA	LAMPANG-2	121115770	HN	CHN	1053	DONGCHUAN	075004320	200	7.79
	THA	LAMPANG-2	121115770	HN	CHN	1053	LIJIANG	075004321	140	7.29
	THA	LAMPANG-2	121115770	HN	CHN	1053	LINCANG	075004322	200	9.98
	THA	LAMPANG-2	121115770	HN	CHN	1053	LUCHUN	075004323	280	9.35
	THA	LAMPANG-2	121115770	HN	CHN	1053	LUXI	075004324	140	9.08
	THA	LAMPANG-2	121115770	HN	CHN	1053	WENSHAN XIAN	075004325	280	8.31
	THA	LAMPANG-2	121115770	HN	CHN	1053	XIAGUAN	075004326	180	8.84
1116	THA	PHITSANULOK-3	121115759	HN	CHN	1116	DUKOU	075004779	240	0.73
1188	THA	PHITSANULOK-5	121115758	HN	CHN	1188	KUNMING	075005265	260	1.04
	THA	SA KAE0-1	121115718	HN	CHN	1188	KUNMING	075005265	220	2.69
1197	THA	LOP BURI-4	121115722	HN	CHN	1197	CHUXIONG	075005319	140	1.48
	THA	LOP BURI-4	121115722	HN	CHN	1197	PUER	075005320	60	1.40
	THA	LOP BURI-4	121115722	HN	CHN	1197	WENSHAN	075005322	20	1.70
	THA	LOP BURI-4	121115722	HN	CHN	1197	YUNLONG	075005323	80	0.60
1215	THA	UBON RATCHATHANI-4	121115755	HN	CHN	1215	DINGNAN	075005455	260	0.60
	THA	UBON RATCHATHANI-4	121115755	HN	CHN	1215	HUIZHOU	075005464	240	0.80
	THA	UBON RATCHATHANI-4	121115755	HN	CHN	1215	YINGDE	075005504	240	0.97
	THA	UBON RATCHATHANI-4	121115755	HN	CHN	1215	ZHANJIANG	075005508	220	3.45
1242	THA	PHETCHABUN-3	121115745	HN	CHN	1242	BIJIANG	075005713	120	2.32
	THA	PHETCHABUN-3	121115745	HN	CHN	1242	BINCHUAN	075005714	140	3.06
	THA	PHETCHABUN-3	121115745	HN	CHN	1242	CHANGNING	075005715	180	3.46
	THA	PHETCHABUN-3	121115745	HN	CHN	1242	GEJIU	075005716	260	3.36
	THA	PHETCHABUN-3	121115745	HN	CHN	1242	JINGHONG	075005717	220	4.79
	THA	PHETCHABUN-3	121115745	HN	CHN	1242	QUJING	075005718	240	2.85
	THA	PHETCHABUN-3	121115745	HN	CHN	1242	ZHAOTONG	075005719	180	2.14
1287	THA	UTTARADIT-1	121115732	HN	CHN	1287	HAIYUAN	075006010	240	0.65
1305	THA	SARABURI-3	121115750	HN	CHN	1305	BEIHAI	075006107	280	0.84
	THA	SARABURI-3	121115750	HN	CHN	1305	BOSE	075006109	280	0.88
	THA	SARABURI-3	121115750	HN	CHN	1305	DONGCHUAN	075006118	180	1.48
	THA	SARABURI-3	121115750	HN	CHN	1305	DUKOU	075006119	180	1.32

Annex to affected administration

CHN

Modification to the Plan					Affected assignment in the Plan				Worst affected point	
Freq	Ctry	Site name	Id No	HJ/HN	Ctry	Freq	Site name	Id No	Azm	Eu_Inc
	THA	SARABURI-3	121115750	HN	CHN	1305 GUIYANG		075006125	200	0.50
	THA	SARABURI-3	121115750	HN	CHN	1305 HECHI		075006128	200	0.70
	THA	SARABURI-3	121115750	HN	CHN	1305 HEKOU		075006129	220	1.95
	THA	SARABURI-3	121115750	HN	CHN	1305 LIJIANG		075006138	140	1.13
	THA	SARABURI-3	121115750	HN	CHN	1305 LINCANG		075006139	40	1.82
	THA	SARABURI-3	121115750	HN	CHN	1305 LUCHUN		075006142	140	2.06
	THA	SARABURI-3	121115750	HN	CHN	1305 LUXI		075006143	100	1.11
	THA	SARABURI-3	121115750	HN	CHN	1305 NANNING		075006146	140	0.79
	THA	SARABURI-3	121115750	HN	CHN	1305 PINGLE		075006149	180	0.56
	THA	SARABURI-3	121115750	HN	CHN	1305 QIUBEI		075006153	200	1.67
	THA	SARABURI-3	121115750	HN	CHN	1305 WEINING		075006168	220	1.13
	THA	SARABURI-3	121115750	HN	CHN	1305 XIAGUAN		075006171	100	1.50
	THA	SARABURI-3	121115750	HN	CHN	1305 XINGYI		075006175	180	1.47
	THA	SARABURI-3	121115750	HN	CHN	1305 YOUYANG		075006184	40	0.50
	THA	SARABURI-3	121115750	HN	CHN	1305 YULIN 2		075006185	140	0.73
1359	THA	SAKON NAKHON-3	121115762	HN	CHN	1359 ANSHUN SHI		075006615	180	3.85
	THA	SAKON NAKHON-3	121115762	HN	CHN	1359 BIJIE		075006619	180	3.34
	THA	SAKON NAKHON-3	121115762	HN	CHN	1359 BINCHUAN		075006620	100	3.04
	THA	SAKON NAKHON-3	121115762	HN	CHN	1359 CHANGNING		075006623	60	2.80
	THA	SAKON NAKHON-3	121115762	HN	CHN	1359 CHANGTING		075006624	240	0.92
	THA	SAKON NAKHON-3	121115762	HN	CHN	1359 CHENGKOU		075006625	240	0.57
	THA	SAKON NAKHON-3	121115762	HN	CHN	1359 DEJIANG		075006627	220	2.14
	THA	SAKON NAKHON-3	121115762	HN	CHN	1359 FENGJIE		075006628	260	0.75
	THA	SAKON NAKHON-3	121115762	HN	CHN	1359 GARZE		075006630	180	1.13
	THA	SAKON NAKHON-3	121115762	HN	CHN	1359 GEJIU		075006631	120	5.47
	THA	SAKON NAKHON-3	121115762	HN	CHN	1359 GUI XIAN		075006633	240	4.29
	THA	SAKON NAKHON-3	121115762	HN	CHN	1359 JINGHONG		075006644	60	3.08
	THA	SAKON NAKHON-3	121115762	HN	CHN	1359 KANGDING		075006646	180	2.05
	THA	SAKON NAKHON-3	121115762	HN	CHN	1359 LESHAN		075006650	200	2.31
	THA	SAKON NAKHON-3	121115762	HN	CHN	1359 LUODIAN		075006652	180	4.28
	THA	SAKON NAKHON-3	121115762	HN	CHN	1359 LUSHUI XIAN		075006618	60	2.49
	THA	SAKON NAKHON-3	121115762	HN	CHN	1359 LUZHOU		075006654	200	2.49
	THA	SAKON NAKHON-3	121115762	HN	CHN	1359 MAQEN		075006655	160	0.50
	THA	SAKON NAKHON-3	121115762	HN	CHN	1359 MIAN XIAN		075006657	180	0.54

Annex to affected administration

CHN

Modification to the Plan					Affected assignment in the Plan				Worst affected point	
Freq	Ctry	Site name	Id No	HJ/HN	Ctry	Freq	Site name	Id No	Azm	Eu_Inc
	THA	SAKON NAKHON-3	121115762	HN	CHN	1359	NANCHONG SHI	075006658	200	1.34
	THA	SAKON NAKHON-3	121115762	HN	CHN	1359	PINGXIANG 2	075006663	320	6.82
	THA	SAKON NAKHON-3	121115762	HN	CHN	1359	QINGLONG	075006665	200	4.48
	THA	SAKON NAKHON-3	121115762	HN	CHN	1359	QINZHOU	075006666	220	5.64
	THA	SAKON NAKHON-3	121115762	HN	CHN	1359	QUJING	075006668	160	4.82
	THA	SAKON NAKHON-3	121115762	HN	CHN	1359	RONGJIANG	075006669	220	3.37
	THA	SAKON NAKHON-3	121115762	HN	CHN	1359	SERXU	075006670	160	0.71
	THA	SAKON NAKHON-3	121115762	HN	CHN	1359	SHIBING	075006673	220	2.53
	THA	SAKON NAKHON-3	121115762	HN	CHN	1359	WAYUAN XIAN	110014935	60	2.72
	THA	SAKON NAKHON-3	121115762	HN	CHN	1359	XIANGCHENG	075006682	120	2.11
	THA	SAKON NAKHON-3	121115762	HN	CHN	1359	YINGJIANG XIAN	110014928	80	2.30
	THA	SAKON NAKHON-3	121115762	HN	CHN	1359	ZHAOJUE	075006686	160	3.03
	THA	SAKON NAKHON-3	121115762	HN	CHN	1359	ZHAOTONG	075006687	160	3.30
	THA	SAKON NAKHON-3	121115762	HN	CHN	1359	ZHENKANG XIAN	110014936	0	2.52
	THA	SAKON NAKHON-3	121115762	HN	CHN	1359	ZIGONG	075006691	200	2.20
	THA	SAKON NAKHON-3	121115762	HN	CHN	1359	ZUNYI SHI	075006693	180	2.69
1440	THA	NAKHON PHANOM-2	121115742	HN	CHN	1440	HE XIAN	075007274	220	1.65
	THA	NAKHON PHANOM-2	121115742	HN	CHN	1440	LINGSHAN	075007275	240	4.00
	THA	NAKHON PHANOM-2	121115742	HN	CHN	1440	LIUZHOU	075007276	200	3.06
	THA	NAKHON PHANOM-2	121115742	HN	CHN	1440	LONGLIN	075007277	180	3.98
	THA	NAKHON PHANOM-2	121115742	HN	CHN	1440	PINGGUO	075007278	200	4.65
	THA	NAKHON PHANOM-2	121115742	HN	CHN	1440	PINGNAN	075007279	220	2.78
	THA	NAKHON PHANOM-2	121115742	HN	CHN	1440	QUANZHOU 2	075007280	220	1.24
1467	THA	PATHUM THANI-7	121115701	HN	CHN	1467	CHENGDU	075007484	220	1.80

Annex to affected administration

D

Modification to the Plan					Affected assignment in the Plan				Worst affected point	
Freq	Ctry	Site name	Id No	HJ/HN	Ctry	Freq	Site name	Id No	Azm	Eu_Inc
1539	I	MURIS-RAGOGNA	121131682	HN	D	1539	MAINFLINGEN	075008838	140	0.84

Annex to affected administration

HRV

Modification to the Plan					Affected assignment in the Plan				Worst affected point	
Freq	Ctry	Site name	Id No	HJ/HN	Ctry	Freq	Site name	Id No	Azm	Eu_Inc
1377	I	GORIZIA	121131679	HJ	HRV	1377	KUMROVEC	075006898	280	1.51

Annex to affected administration

IND

Modification to the Plan					Affected assignment in the Plan				Worst affected point	
Freq	Ctry	Site name	Id No	HJ/HN	Ctry	Freq	Site name	Id No	Azm	Eu_Inc
612	THA	CHIANG MAI-1	121115695	HN	IND	612	AIJAL	075000836	100	2.14
621	THA	KHON KAEN-2	121115699	HN	IND	621	PATNA	075000893	120	1.26
684	THA	N SITHAMMARAT-2	121115769	HJ	IND	684	PT BLAIR	075001423	120	12.23
	THA	N SITHAMMARAT-2	121115769	HN	IND	684	PT BLAIR	075001423	80	4.86
	THA	UDON THANI-1	121115767	HN	IND	684	PT BLAIR	075001423	80	0.53
738	THA	SONGKHLA-2	121115725	HJ	IND	738	PT BLAIR	075001865	140	2.88
828	THA	SUKHOTHAI-1	121115726	HN	IND	828	SILCHAR	075002548	160	4.73
1053	THA	LAMPANG-2	121115770	HN	IND	1053	TUTICORIN	075004345	140	0.56
1269	THA	BANGKOK-23	121115747	HN	IND	1269	AGARTALA	075005903	140	2.64
	THA	SONGKHLA-4	121115697	HN	IND	1269	AGARTALA	075005903	300	0.62
1404	THA	SONGKHLA-5	121115700	HN	IND	1404	TEZPUR	075007040	200	0.85
	THA	SUPHAN BURI-1	121115760	HN	IND	1404	TEZPUR	075007040	180	0.78

Annex to affected administration

INS

<i>Modification to the Plan</i>					<i>Affected assignment in the Plan</i>				<i>Worst affected point</i>	
<i>Freq</i>	<i>Ctry</i>	<i>Site name</i>	<i>Id No</i>	<i>HJ/HN</i>	<i>Ctry</i>	<i>Freq</i>	<i>Site name</i>	<i>Id No</i>	<i>Azm</i>	<i>Eu_Inc</i>
684	THA	N SITHAMMARAT-2	121115769	HN	INS	684	Depok-1	120234554	0	1.06
738	THA	SONGKHLA-2	121115725	HN	INS	738	Tangerang-1	120234558	280	0.68
747	THA	BANGKOK-7	121115724	HN	INS	747	BENGKULU-1	075001919	20	0.57
	THA	UDON THANI-2	121115734	HN	INS	747	BENGKULU-1	075001919	20	0.65
855	THA	PRACHIN BURI-1	121115714	HN	INS	855	MEDAN	075002809	340	4.99
936	THA	PATTANI-1	121115731	HN	INS	936	Sukabumi-1	120234572	0	1.10
1044	THA	N SITHAMMARAT-4	121115736	HN	INS	1044	SIBOLGA	075004283	20	8.28
1179	THA	BANGKOK-20	121115710	HN	INS	1179	PADANG-1	075005236	340	2.65
1269	THA	BANGKOK-23	121115747	HN	INS	1269	PONTIANAK	075005909	280	0.92
	THA	SONGKHLA-4	121115697	HN	INS	1269	PONTIANAK	075005909	240	0.56
1287	THA	UTTARADIT-1	121115732	HN	INS	1287	PALEMBANG	075006021	0	0.57
1404	THA	SONGKHLA-5	121115700	HN	INS	1404	DJAKARTA	075007042	0	2.55
1467	THA	PATHUM THANI-7	121115701	HN	INS	1467	Tanjungpinang-2	075007500	340	10.06
1530	THA	CHANTHABURI-5	121115743	HN	INS	1530	PADANG	075008788	320	3.39

Annex to affected administration

MLA

Modification to the Plan					Affected assignment in the Plan				Worst affected point	
Freq	Ctry	Site name	Id No	HJ/HN	Ctry	Freq	Site name	Id No	Azm	Eu_Inc
594	THA	BANGKOK-3	121115715	HN	MLA	594 KAJANG		075000710	320	3.44
612	THA	CHIANG MAI-1	121115695	HN	MLA	612 KANGAR		075000845	260	0.60
621	THA	KHON KAEN-2	121115699	HN	MLA	621 SEGAMAT		075000903	260	3.41
666	THA	SURIN-1	121115752	HN	MLA	666 PENANG		075001308	0	1.61
	THA	TAK-1	121115720	HN	MLA	666 PENANG		075001308	280	0.86
774	THA	RAYONG-1	121115730	HN	MLA	774 SELAMA		075002207	0	7.60
828	THA	N SITHAMMARAT-3	121115749	HJ	MLA	837 KOTA BAHRU		075002604	340	2.74
936	THA	PATTANI-1	121115731	HJ	MLA	945 TRONOH		075003461	0	1.10
945	THA	KALASIN-1	121115712	HN	MLA	945 JOHORE BAHRU		075003460	40	3.23
	THA	KALASIN-1	121115712	HN	MLA	945 TRONOH		075003461	20	4.70
963	THA	BANGKOK-13	121115728	HN	MLA	963 KUALATRENGGANU		075003585	40	2.12
1008	THA	NAKHON RATCHASIMA-3	121115733	HN	MLA	1008 MALACCA		075003949	20	0.94
1044	THA	N SITHAMMARAT-4	121115736	HN	MLA	1044 SIMANGGANG		075004286	240	0.55
1053	THA	BANGKOK-16	121115737	HN	MLA	1053 MERSING		075004353	80	0.71
	THA	LAMPANG-2	121115770	HN	MLA	1053 MERSING		075004353	80	0.93
1080	THA	YALA-3	121115739	HJ	MLA	1089 GRIK		075004618	0	9.10
1098	THA	SONGKHLA-3	121115709	HJ	MLA	1089 GRIK		075004618	340	2.64
1107	THA	KHON KAEN-5	121115729	HN	MLA	1107 TEMERLOH		075004752	60	0.88
	THA	SAMUT SAKHON-1	121115696	HN	MLA	1107 TEMERLOH		075004752	0	3.13
1188	THA	PHITSANULOK-5	121115758	HN	MLA	1188 KANGAR		075005292	0	0.83
	THA	SA KAE0-1	121115718	HN	MLA	1188 KANGAR		075005292	20	6.17
1269	THA	SONGKHLA-4	121115697	HJ	MLA	1260 KUALA DUNGUN		075005865	40	0.53
1314	THA	KHON KAEN-7	121115698	HN	MLA	1314 MERSING		075006293	0	0.88
1404	THA	SONGKHLA-5	121115700	HN	MLA	1395 KUANTAN		075006988	260	1.06
1440	THA	NAKHON PHANOM-2	121115742	HN	MLA	1440 TEMERLOH		075007305	80	0.52
1530	THA	CHANTHABURI-5	121115743	HN	MLA	1530 BINTULU		075008799	260	1.80

Annex to affected administration

MNE

Modification to the Plan				Affected assignment in the Plan				Worst affected point	
Freq	Ctry	Site name	Id No	HJ/HN	Ctry	Freq	Site name	Id No	Azm Eu_Inc
1503	I	TRIESTE MUGGIA	121131680	HJ	MNE	1503	ULCINJ	075008642	300 0.54

Annex to affected administration

SNG

Modification to the Plan					Affected assignment in the Plan				Worst affected point	
Freq	Ctry	Site name	Id No	HJ/HN	Ctry	Freq	Site name	Id No	Azm	Eu_Inc
792	THA	BANGKOK-8	121115693	HN	SNG	792	SINGAPORE 1	075002332	280	0.52
828	THA	N SITHAMMARAT-3	121115749	HN	SNG	828	SINGAPORE 1	075002568	240	2.11
	THA	SUKHOTHAI-1	121115726	HN	SNG	828	SINGAPORE 1	075002568	320	1.00

Annex to affected administration

VTN

<i>Modification to the Plan</i>					<i>Affected assignment in the Plan</i>				<i>Worst affected point</i>	
<i>Freq</i>	<i>Ctry</i>	<i>Site name</i>	<i>Id No</i>	<i>HJ/HN</i>	<i>Ctry</i>	<i>Freq</i>	<i>Site name</i>	<i>Id No</i>	<i>Azm</i>	<i>Eu_Inc</i>
585	THA	PHRAE-1	121115719	HN	VTN	585	NHATRANG	075000678	280	2.04
594	THA	BANGKOK-3	121115715	HJ	VTN	594	VOV Da Nang 594 kHz	114137900	240	1.02
612	THA	CHIANG MAI-1	121115695	HN	VTN	612	SAIGON	075000867	0	0.70
783	THA	KAMPHAENG PHET-1	121115773	HN	VTN	783	CANTHO	075002284	0	0.68
	THA	RANONG-1	121115704	HJ	VTN	783	CANTHO	075002284	260	2.50
828	THA	N SITHAMMARAT-3	121115749	HJ	VTN	828	Tien Giang 828 kHz	114137910	300	0.77
	THA	SUKHOTHAI-1	121115726	HJ	VTN	828	Son La 828 kHz	114137882	240	9.76
	THA	SUKHOTHAI-1	121115726	HN	VTN	828	Son La 828 kHz	114137882	240	2.44
	THA	SUKHOTHAI-1	121115726	HN	VTN	828	Tien Giang 828 kHz	114137910	280	0.50